

Figure 4: East-facing section through motte within Trench 1




Figure 5: North-facing section through motte within Trench 1




Figure 6: Exposed elevation of Castle foundation wall within Trench 1

KEY



Sandstone



Slate



Unclear boundary
between contexts

1:20 @ A3

