

Lord Crewe Arms - Historic Building Record
OASIS No. 194250
Index of Photos Plates 1-40

| | |
|----------|---|
| Plate 1 | North Elevation Showing Medieval Nave Wall |
| Plate 2 | South-East Elevation Showing Lancet Window of Former Abbey Nave |
| Plate 3 | Half Round Pilaster North Elevation Facing Churchyard |
| Plate 4 | Double Piscina North Elevation Facing Churchyard |
| Plate 5 | North Elevation Showing Part of Window Jamb |
| Plate 6 | Doorway in Wall South Elevation East of Tower |
| Plate 7 | East Elevation First Floor Window to Bamburgh Room |
| Plate 8 | View of Stained Glass Window from Bamburgh Room |
| Plate 9 | Close Up of Stained Glass Window |
| Plate 10 | Close Up of Stained Glass Window |
| Plate 11 | East Elevation Tower Gothic Doorway |
| Plate 12 | Stone Flag Floor to West End of Crypt Bar |
| Plate 13 | Removal of Flags in West End of Crypt Bar for Services and Showing Thickened Out Foundation Wall (Centre Picture) |
| Plate 14 | Removal of Flags in West End of Crypt Bar for Services and Showing Thickened Out Foundation Wall |
| Plate 15 | The Crypt Bar |
| Plate 16 | The Crypt Bar East End showing Floor |
| Plate 17 | Excavation in Floor of Crypt Bar Showing Medieval Wall Continuing Over Doorway |
| Plate 18 | Reinstated Floor Above Medieval Wall Over Doorway |
| Plate 19 | Recess in North Wall of Crypt Bar |
| Plate 20 | Stone String Course North Wall of Crypt Bar |
| Plate 21 | The Garderobe Dorothy Forster Room |
| Plate 22 | Internal View of the Garderobe Showing the Square Hole. |
| Plate 23 | Hob Grate Fireplace in Dorothy Forster Room |
| Plate 24 | Hob Grate Fireplace in Bamburgh Room |
| Plate 25 | Fireplace Feature in Shower of Bamburgh Room. |
| Plate 26 | Fireplace in Radcliffe Room with Recess Above |
| Plate 27 | Oak Beam Roof Construction in the Radcliffe Room |
| Plate 28 | Chamfered Stop to Beam in Radcliffe Room |

Lord Crewe Arms - Historic Building Record
OASIS No. 194250
Index of Photos Plates 1-40

| | |
|----------|--|
| Plate 29 | Corbel to Ridge Piece in Radcliffe Room |
| Plate 30 | Quoin Stones to Tower East Elevation |
| Plate 31 | Central Section Quoin Stones East Elevation (Far Right) |
| Plate 32 | Central Section Quoin Stones West Elevation (Centre) and Stone Dressing and Window Head Detail |
| Plate 33 | Chimney Breast Within Roof Space above Tom Forster Room |
| Plate 34 | The Dovecote above Tom Forster Room |
| Plate 35 | The Smaller Dovecote above Tom Forster Room |
| Plate 36 | Horace Walpole Style Fireplace in Former Restaurant |
| Plate 37 | View of Former Restaurant and Cupboards |
| Plate 38 | Plank and Ledged Door Entrance to Dorothy Forster Room |
| Plate 39 | Earthenware Sink Entrance to Dorothy Forster Room |
| Plate 40 | Ceiling in the Hilyard Room |

Lord Crewe Arms - Historic Building Record
OASIS No. 194250
Index of Photos Plates 41-81

| | |
|----------|--|
| Plate 41 | View in Hilyard Room Showing Fireplace and Stairs |
| Plate 42 | View from External Entrance Towards Crypt Bar |
| Plate 43 | West Elevation of Cottages |
| Plate 44 | Early Window North Elevation of Cottages West End |
| Plate 45 | View up Stairs from Hilyard Room to Dorothy Forster Room |
| Plate 46 | Stone Chute on East Elevation of North Toilet Extension |
| Plate 47 | Pointed Arch over Door to Crypt Bar from Toilet Extension |
| Plate 48 | View into Lobby of Crypt Bar from Front Entrance Showing Floor and Wall Reinstated |
| Plate 49 | View of Reinstated Floor and Medieval Wall in Lobby to Crypt Bar |
| Plate 50 | Existing Stone Flag Floor Leading to Cottage External Entrance |
| Plate 51 | Reinstatement of Masonry in West End of Crypt Bar after Installation of TV Cable |
| Plate 52 | Existing Entry Position of TV Cable to Crypt Bar |
| Plate 53 | Existing Stone Flag Floor Leading to Gun Store |
| Plate 54 | Door from Stairs Leading to Dorothy Forster Room. |
| Plate 55 | Existing Defective Stone Floor to Beer Store to be Replaced with Concrete |
| Plate 56 | Existing Sealed Window in North Wall of Cottages |
| Plate 57 | Large Fireplace in Hilyard Room |
| Plate 58 | Floor Duct in Derwent Room with Service Hole Through Medieval Wall |
| Plate 59 | Floor Duct in Derwent Room |
| Plate 60 | Existing Stone Flag Floor to Derwent Room |
| Plate 61 | Fireplace in Derwent Room |
| Plate 62 | Floor Service Duct in Fireplace in Hilyard Room |
| Plate 63 | Large Segmental Arch East Elevation of Southern Building |
| Plate 64 | Front Entrance West Elevation |
| Plate 65 | Eighteenth Century Staircase Leading up to Tom Forster Room |
| Plate 66 | Large Segmental Fireplace in Reception |
| Plate 67 | Sculpted Stone Fragment in Roof Space Over Wes. End of Cottages |
| Plate 68 | Window Detail South Elevation of Cottages |

Lord Crewe Arms - Historic Building Record
OASIS No. 194250
Index of Photos Plates 41-81

| | |
|----------|--|
| Plate 69 | Window Jamb South Elevation of Cottages |
| Plate 70 | Sealed up Opening South Elevation of Cottages |
| Plate 71 | Face and Foliage Details on South Wall of Cottages |
| Plate 72 | Former Doorway South Elevation of Cottages West End |
| Plate 73 | New Doorway South Elevation of Cottages West End. New Door under Refurbishment Scheme |
| Plate 74 | Medieval Fireplace in First Floor East Bedroom of Cottages with Cast Iron Grate of Later Date. |
| Plate 75 | Tudor Style Fireplace Surround in Ground Floor Lounge East End of Cottages. |
| Plate 76 | Former Doorway Through First Floor Bedroom Wall of Cottages. |
| Plate 77 | Former Doorway Through First Floor Bedroom Wall of Cottages (Close up). |
| Plate 78 | Eighteenth Century Fireplace Surround First Floor Cottages. |
| Plate 79 | Former Staircase Well Ground Floor Cottages. |
| Plate 80 | Range and Copper in Privies. |
| Plate 81 | External View of New TV Cable Installed Externally to Crypt Bar West Wall. |