


# DEFENCE WORKS AT THE MALTINGS, TRIMLEY ROAD, KIRTON, SUFFOLK A PHOTOGRAPHIC RECORD

Alun Bull and John Minnis



*This report has been prepared for use on the internet and the images within it have been down-sampled to optimise downloading and printing speeds.*

*Please note that as a result of this down-sampling the images are not of the highest quality and some of the fine detail may be lost. Any person wishing to obtain a high resolution copy of this report should refer to the ordering information on the following page.*



ENGLISH HERITAGE

**DEFENCE WORKS  
THE MALTINGS  
TRIMLEY ROAD, KIRTON, SUFFOLK**

**PHOTOGRAPHIC SURVEY**

**Report by:** JOHN MINNIS  
**Research by:** JOHN MINNIS  
**Research date:** 17 OCTOBER 2006  
**Photography by:** ALUN BULL

**NBR No** 109635

**NGR** TM2770239402

**ISSN** 1749-8775

Research Department Report Series 18/2007

© English Heritage

**Comments or queries regarding the content of the report should be made to the author at:**  
ENGLISH HERITAGE, BROOKLANDS, 24 BROOKLANDS AVENUE, CAMBRIDGE CB2 2BU  
**Tel:** 01223 582700 **Fax:** 01223 582708

**Applications for reproduction should be made to:**  
THE NATIONAL MONUMENTS RECORD  
ENGLISH HERITAGE, KEMBLE DRIVE, SWINDON SN2 2GZ  
**Tel:** 01793 414600 **Fax:** 01793 414606 **e-mail:** nmrinfo@english-heritage.org.uk

The National Monuments Record is the public archive of English Heritage  
[www.english-heritage.org.uk](http://www.english-heritage.org.uk)

## The Research Department Report Series

The Research Department Report Series incorporates reports from all the specialist teams within the English Heritage Research Department: Archaeological Science; Archaeological Archives; Historic Interiors Research and Conservation; Archaeological Projects; Aerial Survey and Investigation; Archaeological Survey and Investigation; Architectural Investigation; Imaging, Graphics and Survey, and the Survey of London. It replaces the former Centre for Archaeology Reports Series, the Archaeological Investigation Report Series and the Architectural Investigation Report Series.

Many of these are interim reports which make available the results of specialist investigations in advance of full publication. They are not usually subject to external refereeing, and their conclusions may sometimes have to be modified in the light of information not available at the time of the investigation. Where no final project report is available, readers are advised to consult the author before citing these reports in any publication. Opinions expressed in Research Department reports are those of the author(s) and are not necessarily those of English Heritage.

# **SECOND WORLD WAR DEFENCE WORKS AT THE MALTINGS, KIRTON, SUFFOLK**

---

**NGR: TM2770239402**

## **Report on visit 17 October 2006**

These notes were prepared at the request of Tony Calladine, Team Leader, Heritage Protection, Eastern Territory, English Heritage and are intended to accompany a photographic record of the site and to provide an indication of the physical state of the remains of the defence works on the date visited. They supplement the information included in the detailed report (Lanigan Report) produced by Mr Len Lanigan as part of his submission to English Heritage for buildings on the site to be listed. Included in this report were photographs by Alastair Graham-Kerr of the structures before demolition. The site has also been visited by Roger J. C. Thomas of English Heritage prior to the demolition work.

The following structures were identified in the Lanigan Report as being of significance

A Battery Observation Post  
Two Pocket or Light Anti-aircraft Posts  
A Gun Post.

Since the production of Mr Lanigan's report, the owner of the site has carried out clearance work, felling many trees, removing scrub and undergrowth, although much of the land is still covered with heavy weed growth. Demolition of the observation post and the two light anti-aircraft posts has taken place.

## **Battery Observation Post**

This was apparently demolished by a bulldozer and the remains have been left in situ. The present condition of the structure is that the concrete base remains intact, together with the east wall and part of the splayed south-east wall. The concrete roof is also intact, lying on top of some of the brickwork of the remaining walls. Large sections of the brick walls are lying on the ground. Internally, part of the shelving referred to in the Lanigan Report remains in situ as does the base of the stove and an extraction vent.

## **Pocket or Light Anti-Aircraft Posts**

These have been completely demolished with scattered cement-filled sandbags and some pieces of corrugated iron as the only evidence of their existence. Tree-trunks from the felled trees are mixed in with the remains which are now overgrown and it is difficult to establish their form or exact position.

## **Gun Post**

This has not been affected by the clearance work and is exactly as depicted in the Lanigan report. As that report states, the walls with the exception of part of the west side are substantially intact but the roof slab has fallen in and now forms in effect a floor, itself now overgrown with weeds and small trees.

Although the battery observation post is partly demolished, it is still possible to read the structure in its relationship with the gun post and the relationship of the site of the defence works as a whole with the surrounding landscape.



***Battery Observation Post following demolition from the north west. Roof slab in foreground.***

**© English Heritage DP030170**



***Battery Observation Post from the south east showing portions of brick walling.***

**© English Heritage DP030184**



*Battery Observation Post , shewing internal shelf.*

© English Heritage DP030172



*Battery Observation Post from the north west (detail).*

© English Heritage DP030177





*Remains of Light Anti-Aircraft Post.*

© English Heritage DP030191



*Remains of Light Anti-Aircraft Post, showing construction of cement-filled sandbags.*

© English Heritage DP030189



*Remains of Light Anti-Aircraft Post, showing detail of sandbags.*

© English Heritage DP030190



*Gun Post, from the north east with later shed built up against the structure.*

© English Heritage DP030193



*Gun Post, south east corner.*

© English Heritage DP030196




*Gun Post, south east corner interior.*

© English Heritage DP030197



*Gun Post, interior of east wall.*

© English Heritage DP030194



*Gun Post, interior of north east corner.*

© English Heritage DP030200



## **ENGLISH HERITAGE RESEARCH DEPARTMENT**

*English Heritage undertakes and commissions research into the historic environment, and the issues that affect its condition and survival, in order to provide the understanding necessary for informed policy and decision making, for sustainable management, and to promote the widest access, appreciation and enjoyment of our heritage.*

*The Research Department provides English Heritage with this capacity in the fields of buildings history, archaeology, and landscape history. It brings together seven teams with complementary investigative and analytical skills to provide integrated research expertise across the range of the historic environment. These are:*

- \* Aerial Survey and Investigation*
- \* Archaeological Projects (excavation)*
- \* Archaeological Science*
- \* Archaeological Survey and Investigation (landscape analysis)*
- \* Architectural Investigation*
- \* Imaging, Graphics and Survey (including measured and metric survey, and photography)*
- \* Survey of London*

*The Research Department undertakes a wide range of investigative and analytical projects, and provides quality assurance and management support for externally-commissioned research. We aim for innovative work of the highest quality which will set agendas and standards for the historic environment sector. In support of this, and to build capacity and promote best practice in the sector, we also publish guidance and provide advice and training. We support outreach and education activities and build these in to our projects and programmes wherever possible.*

*We make the results of our work available through the Research Department Report Series, and through journal publications and monographs. Our publication Research News, which appears three times a year, aims to keep our partners within and outside English Heritage up-to-date with our projects and activities. A full list of Research Department Reports, with abstracts and information on how to obtain copies, may be found on [www.english-heritage.org.uk/researchreports](http://www.english-heritage.org.uk/researchreports)*

*For further information visit [www.english-heritage.org.uk](http://www.english-heritage.org.uk)*

