

20th Century Naval Dockyards Devonport and Portsmouth 6265 Record Form Figure nos relate to the published Report		Portsmouth Dockyard Archive: TNA Building Nos: various Building Names: various Grid Ref: SU 63477 01030
Archive name and address	The National Archives, Bessant Dr, Kew, Surrey TW9 4DU.	
Visit date	6 February 2013	
Document reference	ADM 195/79	
Subject	Miscellaneous	
Summarise the salient points of the document	100 photographs depicting construction works at Portsmouth Dockyard: views of features: square-rigged ships including HMS Victory, naval base and damage caused by Zeppelin raid 1915. Dated 1857–1915.	
Identify whether it should be copied for data: Yes/No	Yes	
Identify whether an image should be included in the Report: Yes/No If Yes explain why, as succinctly as possible (its relevance to technology/ chronology/ dockyard development/other/where it fits into the larger picture)	Yes. Volume could clearly provide several illustrations for the final report.	
Give indication of importance: Core/Secondary/Nil	Core	
Researcher initials	JDD	Updates/initials AVC 8.3.16
Figure nos in the published Report	<p>See Coats <i>et al.</i> (2015), p. 136, 139, 143, 144, 160:</p> <p>Fig. 335. Dock No. 1 (6.1.1909). Photograph of completed extension, looking northeast. TNA, ADM 195/79 (1857–1915). 100 photographs depicting construction works at Portsmouth Dockyard. Reproduced with the permission of The National Archives.</p> <p>Fig. 340. Portsmouth Joiners Shop 3.2.1911. TNA, ADM 195/79 (1857–1915). 100 photographs depicting: construction works at Portsmouth Dockyard. Reproduced with the permission of The National Archives.</p> <p>Fig. 357. Storehouse No. 33 before reconstruction after fire 23.3.1908, photograph no. 99. TNA, ADM 195/79 (1857–1915). 100 photographs depicting: construction works at Portsmouth Dockyard. Reproduced with the permission of The National Archives.</p> <p>Fig. 360. Damage to Portsmouth No. 1 Slip Jetty looking east, 1.2.1915, with the Smithery and the Steam Factory in the background. TNA, ADM 195/79 (1857–1915). 100 photographs depicting: construction works at Portsmouth Dockyard. Reproduced with the permission of The National Archives.</p> <p>Fig. 361. Portsmouth No. 2. Slip and S. Side Laying Out Shop looking west, 1.2.14. TNA, ADM 195/79 (1857–1915). 100 photographs depicting: construction works at Portsmouth Dockyard. Reproduced with the permission of The National Archives.</p> <p>Fig. 422. New Anchor Gate 12.9.1907. TNA, ADM 195/79 (1857–1915). 100 photographs depicting: construction works at Portsmouth Dockyard. Reproduced with the permission of The National Archives.</p> <p>Fig. 442. New Portsmouth Pay Room 7.1.1909. TNA, ADM 195/79 (1857–1915). 100 photographs depicting: construction works at Portsmouth Dockyard. Reproduced with the permission of The National Archives.</p> <p>Fig. 443. New Portsmouth Pay Room (interior) 30.3.1909. TNA, ADM 195/79 (1857–1915). 100 photographs depicting: construction works at Portsmouth Dockyard. Reproduced with the permission of The National Archives.</p>	
References	Coats, A., Davies, J. D., Evans, D., and Riley, R. (2015). <i>20th Century Naval Dockyards: Devonport and Portsmouth Characterisation Report</i> .	

Portsmouth: Naval Dockyards Society. ISBN 978-0-9929292-0-6, ebook ISBN 978-0-9929292-2-0.

The Report is free to download on the Naval Dockyards Society website:
<http://navaldockyards.org/c20-naval-dockyards/>