

Figure 3.9 North-facing elevation of window in ?south wall of cloister reconstructed from in situ sill-jamb junction, Area D




Figure 3.10 East-facing section through connecting passage in west range of cloister, Area A