

Appendix 1: Colour Plates



**Plate 2:** G1 looking N/W.



**Plate 3:** G1 looking S/E.



**Plate 4:** G2 looking S/S/W.



**Plate 5:** G3 looking S/S/W.



**Plate 6:** G4 looking S/S/W.



**Plate 7:** G5 looking S/E.



**Plate 8:** G5 looking N/E.



**Plate 9:** G5 Fireplace looking S/S/W.



**Plate 10:** G5 window looking S/W.





**Plate 11:** G5 entrance looking N/W.



**Plate 12:** G6 under stair cupboard looking S/E.



**Plate 13:** G7 looking S/E.



**Plate 14:** G7 looking N/W.




**Plate 15:** G7 looking S/E towards main entrance.



**Plate 16:** G7 looking N/W up stairs



**Plate 17:** G8 looking N/E towards Snug seating.



**Plate 18:** G8 looking N/E towards Snug seating.



**Plate 19:** G8 looking N/W towards Snug seating.





**Plate 20:** G8 looking N/E to fireplace.



**Plate 21:** G8 looking S/E to cupboard.



**Plate 22:** G8 looking S/E to serving hatch and counter.



**Plate 23:** G7 looking N/E into cupboard.



Plate 24: G9 looking N/E.



Plate 25: G9 looking N/W to G10.



Plate 26: G10 looking S/W to serving hatch.



Plate 27: G11 looking N/W to rear exit.



**Plate 28:** G12 looking N/W.



**Plate 29:** G12 looking N/W.





Plate 30: G13 looking N/E.



**Plate 31:** G14 looking N/E.



**Plate 32:** G15 toilet looking N/W.



**Plate 34:** G16 looking S/W.



**Plate 35:** G17 looking S/E.



**Plate 36:** G17 access to loft looking N/E.



Plate 37: G17 stalling looking S/E.



Plate 38: G17 stalling looking N/E.



**Plate 39:** G17 window looking N/W.



**Plate 40:** G17 entrance looking N/W.



**Plate 41:** G17 looking N/E.





**Plate 42:** G17 looking S/E.



**Plate 43:** G18 looking N/E.



**Plate 44:** G18 looking S/E.



Plate 45: G18 looking E.



Plate 46: G18 looking N/W.



**Plate 47:** G18 looking S/W.



**Plate 48:** G18 looking N/W.



**Plate 49:** F19 looking S/E.



**Plate 50:** F19 looking S/E.



**Plate 51:** F19 looking N/W to entrance.



**Plate 52:** F20 looking N/E.



**Plate 53:** F20 looking N/W.





**Plate 54:** F20 looking S/E towards window.



**Plate 55:** F20 looking N/W towards cupboard.



**Plate 56:** F21 looking N/E.



**Plate 57:** F22 looking S/E down stairs.



**Plate 58:** F22 looking S/E.



**Plate 59:** F22 looking N/W.



**Plate 60:** F22 looking S/W towards window.



**Plate 61:** F23 looking N/E.



Plate 62: F23 looking N/E towards window.



Plate 63: F23 looking S/E.





**Plate 64:** F24 looking N/W.



**Plate 65:** F24 looking N/W.



**Plate 66:** F25 looking S/E towards cupboard.



**Plate 67:** F25 looking N/E towards window.



**Plate 68:** F25 looking N/W.



**Plate 69:** Old Greyhound Inn N facing elevation.



**Plate 70:** Old Greyhound Inn E facing elevation.



**Plate 71:** Old Greyhound Inn E facing elevation.



**Plate 72:** Old Greyhound Inn S facing elevation.





**Plate 73:** Old Greyhound Inn S facing elevation.



**Plate 74:** Old Greyhound Inn N facing elevation.



**Plate 75:** Old Greyhound Inn E facing elevation.



**Plate 76:** Old Greyhound Inn N facing elevation.



**Plate 77:** Old Greyhound Inn S facing elevation.



**Plate 78:** Old Greyhound Inn E facing elevation.



**Plate 79:** Stable W facing elevation.



**Plate 80:** Stable E facing elevation.



**Plate 81:** Stable S facing elevation.



**Plate 82:** Stable N facing elevation.