










-  magnetic anomalies  
(possibly archaeological ?)
-  strong magnetic disturbances  
(recent / non-archaeological)
-  background magnetic anomalies  
(mainly natural ?)
-  land drains
-  cultivation
-  strong (ferrous) magnetic anomalies
-  pipe (and associated magnetic  
disturbance)

THE HUB  
SWINDON, WILTSHIRE  
Geophysical Survey 2013  
Figure 5: Magnetometer survey  
(with interpretation)

0 1:1500 100m