



**Plate 1:** The building from the north



**Plate 2:** Main range from the north



**Plate 3:** Western doorway and window from the north



**Plate 4:** Eastern window from the north



**Plate 5:** Brickwork joints from the north



**Plate 6:** Cart shed from the north



**Plate 7:** The building from the south



**Plate 8:** The building from the south east



**Plate 9:** The building from the west



**Plate 10:** West elevation, anomalies in the brickwork



**Plate 11:** West elevation, anomalies in the brickwork



**Plate 12: G1, eastern partition from the south west**



**Plate 13: G1 from the north east**



**Plate 14: G1, window from the south**



**Plate 15: G1, roof truss from the west**





**Plate 16: G2 from the north**



**Plate 17: G2, eastern partition from the south east**



**Plate 18: G2, roof truss from the west**



**Plate 19: G3 from the north**



**Plate 20:** G3, south side of blocked cart entrance from the north west



**Plate 21:** G3, doorway in western partition from the south east



**Plate 22:** G4, south wall from the north west



**Plate 23:** G4, central roof truss from the north



**Plate 24: G4, central roof truss, junction of tie beam and eastern principal**



**Plate 25: G4, central roof truss, junction of eastern principal and raking strut**



**Plate 26: G4, central roof truss, junction of tie beam and king post**



**Plate 27: G4, central roof truss, head of the king post**



**Plate 28: G4, north roof truss from the south**



**Plate 29: F1, roof truss from the west**



**Plate 30:** The farmhouse from the south west