

Context/record sheet

A		Location <u>GATE</u>		Grid ref.		Site code <u>BEG 88</u>		Context/Record no. <u>(66)</u>		
		Category <u>STRUCTURE</u>				Form		Orientation		
B		Length		Width		Diameter		Height/Depth		
		Co-ordinates				Level				
						T.B.M. =		B.S. = +		
		Plan no.		Section no.		Photo b/w <u>6/42</u>		Photo c.		
Soil	Colour			Type <u>7/37-40, 7/3-4, 10/33-8</u> <u>BRICK</u>						
	Consistence			Inclusions						
Structure	Building materials		Unit sizes		Coursing/Bond					
					Bonding material					
C Description and comments										
<p><u>Southern end of barbarian brickwork Bricks 26 x 13 - 27 x 14 mm</u> <u>Slightly stepped foundations or base, overlying a wooden side-plate</u> <u>65. The bottom four courses of brickwork simply abut the</u> <u>main body of the brickwork. Above this the bricks are</u> <u>banded into the main fabric with alternate courses of</u> <u>projecting headers.</u></p>										
Date encountered			Excavation method			% Level of disturbance				
D Stratigraphic relationships										
		Soil			Cut Feature			Structure		
Earlier than	Below		Below			Below				
	Sealed by		Cut by			Butted by				
	Overlapped by		Contains			Cut by				
	Cut by					Encloses				
Contemp with	Part of		Part of			Part of				
	Merges with		Includes			Joined with				
	Includes									
Later than	Above		Cut from			Above <u>(65) (77)</u>				
	Seals		Cuts			Butted to				
	Overlaps					Cuts				
	Lies against					Driven into				
	Contained by					Contained by				
Same as			Characteristically similar to							
E Provisional interpretation										
Note book refs.					Matrix		Phase		Date	
F										
Finds	Pottery			Recorded finds						
	Animal bone									
Samples	Soil	Wood	R/Carbon	Masonry	Brick	Tile	Slag			
G Originator(s)					Checked by			Date		

Humberside Archaeological Unit

A	Location <u>DITCH</u>		Grid ref.		Site code <u>BEG 88</u>		Context/ Record no. <u>(68)</u>							
	Category <u>LAYER</u>				Form		Orientation							
B	Length		Width		Diameter		Height/Depth							
	Co-ordinates				Level									
	: : :				T.B.M.=		B.S.= +		F.S.= -					
	Plan no.			Section no.		Photo b/w		Photo c.						
	Soil	Colour <u>BLACK</u>				Type <u>CLAY, SILTY</u>								
Consistence				Inclusions										
Structure	Building materials		Unit sizes		Coursing/Bond									
					Bonding material									
C	Description and comments													
	<u>BLACK SILTY CLAY INCORPORATING LARGE COBBLES + BRICK + TILE FRAGS. UNDERLIES BRICK FLOOR (54) ON WEST SIDE OF BARBICAN. AT LEAST ONE LARGE LIMESTONE FRAG. (ROUGHLY DRESSED BLOCK) UNDERLYING THIS FLOOR.</u>													
Date encountered			Excavation method			% Level of disturbance								
D	Stratigraphic relationships													
	Earlier than	Soil		Cut Feature			Structure							
		Below <u>(54)</u>		Below			Below							
		Sealed by		Cut by			Butted by							
		Overlapped by		Contains			Cut by							
	Contemp with	Part of		Part of			Part of							
		Merges with		Includes			Joined with							
		Includes												
	Later than	Above		Cut from			Above							
		Seals		Cuts			Butted to							
Overlaps					Cuts									
Lies against					Driven into									
Contained by					Contained by									
Same as		Characteristically similar to												
E	Provisional interpretation													
Note book refs.				Matrix		Phase		Date						
F	Finds		Recorded finds											
	<u>Pottery</u> ✓ Animal bone													
Samples	Soil		Wood		R/Carbon		Masonry		Brick		Tile		Slag	
G	Originator(s)						Checked by			Date				

A	Location <i>GATE</i>		Grid ref.		Site code <i>BEG 88</i>		Context/Record no. <i>(69)</i>			
	Category <i>LAYER</i>				Form		Orientation			
B	Length			Width		Diameter		Height/Depth		
	Co-ordinates				Level					
	: : :				T.B.M. =		B.S. = +		F.S. = -	
	Plan no.			Section no.			Photo b/w		Photo c.	
	Soil	Colour <i>DARK GREEN</i>				Type <i>CLAY</i>				
Consistence				Inclusions						
Structure	Building materials		Unit sizes		Coursing/Bond					
					Bonding material					
C	Description and comments									
	<p><i>Fill from between vertical timbers (57) + (58) = Horizontal plank</i></p> <p><i>(43) Dark green waterlogged clay, with a large (60%) organic content</i></p>									
Date encountered			Excavation method			% Level of disturbance				
D	Stratigraphic relationships									
	Earlier than	Soil			Cut Feature			Structure		
		Below <i>(18)</i>			Below			Below		
		Sealed by			Cut by			Butted by		
		Overlapped by			Contains			Cut by		
	Cut by <i>(68)</i>						Encloses			
	Contemp with	Part of			Part of			Part of		
		Merges with			Includes			Joined with		
		Includes								
	Later than	Above			Cut from			Above		
		Seals			Cuts			Butted to		
		Overlaps						Cuts		
		Lies against						Driven into		
Contained by						Contained by				
Same as			Characteristically similar to							
E	Provisional interpretation									
Note book refs.			Matrix		Phase		Date			
F	Finds		Recorded finds							
	Pottery <input checked="" type="checkbox"/>									
Animal bone										
Samples	Soil	Wood	R/Carbon	Masonry	Brick	Tile	Slag			
G	Originator(s)				Checked by			Date		

A	Location	DITCH		Grid ref.	Site code	BEG 88		Context/Record no.	(70)				
	Category	LAYER			Form	Orientation							
B	Length	Width			0.85		Diameter	Height/Depth				0.32	
	Co-ordinates				Level		T.B.M.=					BS.= +	FS.= -
	Plan no.			Section no.			12		Photo b/w		8/36-7		Photo c.
	Soil	Colour				Type							DEMOLITION RUBBLE
Consistence				Inclusions									
Structure	Building materials		Unit sizes		Coursing/Bond								
					Bonding material								
C	Description and comments												
	Layer of Heavy demolition rubble in ^{west} section. Above brick floor												
	(54). (1)												
	Appears to be cut by a pit infilled with layers (52) — see section drawing												
Date encountered			Excavation method				% Level of disturbance						
D	Stratigraphic relationships												
	Earlier than	Soil			Cut Feature				Structure				
		Below (2) (16) (17)			Below				Below				
		Sealed by			Cut by				Butted by				
		Overlapped by			Contains				Cut by				
	Cut by (52)							Encloses					
	Contemp with	Part of			Part of				Part of				
		Merges with			Includes				Joined with				
		Includes											
	Later than	Above (67) (54)			Cut from				Above				
		Seals			Cuts				Butted to				
		Overlaps							Cuts				
		Lies against							Driven into				
Contained by							Contained by						
Same as			Characteristically similar to										
E	Provisional interpretation												
Note book refs.					Matrix		Phase		Date				
F	Finds	Pottery			Recorded finds								
		Animal bone											
	Samples	Soil	Wood	R/Carbon	Masonry	Brick	Tile	Slag					
G	Originator(s)				Checked by				Date				

Context/record sheet

A Location <u>GATE</u> Grid ref.		Site code <u>BEG 88</u>		Context/Record no. <u>(71)</u>			
		Category <u>TIMBER</u>		Form		Orientation <u>N-S</u>	
B Length <u>0.65m +</u>		Width <u>0.17m</u>		Diameter		Height/Depth <u>0.19m</u>	
Co-ordinates				Level			
				T.B.M. =		B.S. = +	
				F.S. = -			
Plan no. <u>7</u>			Section no. <u>19, T3</u>			Photo b/w <u>11/32-5</u>	Photo c.
Soil	Colour			Type <u>11/3-7</u>			
	Consistence			<u>OAK</u>			
Structure	Building materials		Unit sizes		Coursing/Bond		
					Bonding material		
C Description and comments							
<u>DIAGONAL BRACE JOINTED INTO BEAM 72, IN WALL (74)</u>							
<u>SQUARED OAK BEAM CHAMFERED ON ONE FACE (UNDERSIDE OF JOINT),</u>							
<u>TENONED INTO BEAM (72) WITH A CHASE MORTISE, THE TENON WAS</u>							
<u>0.12m DEEP, MEASURING 0.19m x 0.045m IN SIZE, AND SECURED</u>							
<u>WITH A SINGLE PIEG-HOLE 0.03m IN DIAMETER</u>							
<u>BRACE ANGLED TOWARDS THE NORTH SET AT AN ANGLE OF ABOUT 50°</u>							
Date encountered		Excavation method			% Level of disturbance		
D Stratigraphic relationships							
		Soil		Cut Feature		Structure	
Earlier than	Below			Below			Below
	Sealed by			Cut by			Butted by <u>(72)</u>
	Overlapped by			Contains			Cut by
	Cut by						Encloses
Contemp with	Part of			Part of			Part of
	Merges with			Includes			Joined with <u>(72)</u>
	Includes						
Later than	Above			Cut from			Above
	Seals			Cuts			Butted to
	Overlaps						Cuts
	Lies against						Driven into
	Contained by						Contained by
Same as		Characteristically similar to					
E Provisional interpretation							
Note book refs.				Matrix		Phase	Date
F Finds	Pottery			Recorded finds			
	Animal bone						
Samples	Soil	Wood	R/Carbon	Masonry	Brick	Tile	Slag
G Originator(s)				Checked by			Date

Humberside Archaeological Unit

A	Location <u>GATE</u>		Grid ref.		Site code <u>BEG 88</u>		Context/Record no. <u>(72)</u>	
	Category <u>TIMBER</u>				Form		Orientation <u>N-S</u>	
B	Length <u>1.25m +</u>		Width <u>0.28m</u>		Diameter		Height/Depth <u>0.25m</u>	
	Co-ordinates				Level			
					T.B.M. =		B.S. = +	
					F.S. = -			
Plan no. <u>522 : 8</u>			Section no. <u>19 : 74 : 522</u>			Photo b/w <u>11/32-5</u>		Photo c.
Soil	Colour				Type <u>OAK</u>			
	Consistence				Inclusions			
Structure	Building materials		Unit sizes		Coursing/Bond			
					Bonding material			
C Description and comments								
<u>HORIZONTAL BEAM BELOW WALL (74)</u>								
<u>UNDATED</u>								
<u>SQUARED BEAM BEARING MORTISE HOLE (RECTANGULAR), 0.30 m. x</u>								
<u>0.06 m IN SIZE, FOR DIAGONAL BRACE (71). MENON SECURED IN CHASE</u>								
<u>MORTISE BY A SINGLE^{oval} DOWEL HOLE, 0.07 x 0.04 m. IN SIZE. BEAM</u>								
<u>IS CHAMFERED ON BOTH LOWER SIDES</u>								
<u>SEALED BY LIMESTONE WALLING (74).</u>								
<u>THE SOUTH END OF THE BEAM HAS BEEN BROKEN THROUGH, & PUSHED</u>								
<u>DOWNWARDS BY THE COFFER DAM.</u>								
<u>THE NORTHERN END OF THE BEAM OVERLIES (55), & APPEARS TO ENCASE IT IN A FACE TO FACE</u>								
<u>LAP JOINT.</u>								
Date encountered			Excavation method			% Level of disturbance		
D Stratigraphic relationships								
Earlier than	Soil		Cut Feature			Structure <u>(74)</u>		
	Below		Below		Below			
	Sealed by		Cut by		Butted by			
	Overlapped by		Contains		Cut by			
Contemp with	Part of		Part of			Part of		
	Merges with		Includes			Joined with <u>(71)</u>		
	Includes							
Later than	Above		Cut from			Above <u>55</u>		
	Seals		Cuts			Butted to		
	Overlaps					Cuts		
	Lies against					Driven into		
Contained by					Contained by			
Same as			Characteristically similar to					
E Provisional interpretation								
<u>EASTERN SOLE PLATE OF PHASE 1 GATE.</u>								
Note book refs.			Matrix		Phase		Date	
F Finds	Pottery				Recorded finds			
	Animal bone							
Samples	Soil	Wood	R/Carbon	Masonry	Brick	Tile	Slag	DENDRO
G Originator(s)					Checked by		Date	

Context/record sheet

A Location <u>GATE</u>		Grid ref.		Site code <u>BEG 88</u>		Context/Record no. <u>(73)</u>	
Category <u>TIMBER</u>				Form		Orientation	
B Length <u>0.79m +</u>		Width <u>0.23 m</u>		Diameter		Height/Depth <u>0.22 m</u>	
Co-ordinates				Level			
				T.B.M.=		B.S.= +	
				F.S.= -			
Plan no. <u>7</u>			Section no. <u>16, 17: T1, T2.</u>			Photo b/w <u>7/6</u>	Photo c.
Soil	Colour			Type <u>11/10-12</u>			
	Consistence			Inclusions			
Structure	Building materials		Unit sizes		Coursing/Bond		
					Bonding material		
C Description and comments <u>BACK</u>							
<p><u>DIAGONAL BRACE JOINTED INTO BEAM (55), BELOW WALL (7)</u></p> <p><u>SQUARED OAK TIMBER BEARING CRAMP MARKS ON ONE FACE TRIMMED ON THE INNER FACE OF THE JOINT WITH BEAM (55). SECURED TO THAT BEAM WITH A CHASE MORTISE. THE JOINT WAS FASTENED BY TWO WOODEN DOWELS PASSING THROUGH THE ENTIRE THICKNESS OF (55). THE DOWELS WERE 30mm DIAMETER.</u></p> <p><u>THE TENON MEASURED 0.12 m x 0.155 m</u></p> <p><u>THE BRACE SLANTED TOWARDS THE WEST, IMPLYING THAT IT SERVED AS A BACK-BRACE TO THE FRONT OF THE GATE. SET AT AN ANGLE OF 65°-70°</u></p>							
Date encountered			Excavation method			% Level of disturbance	
D Stratigraphic relationships							
	Soil			Cut Feature		Structure	
Earlier than	Below			Below		Below	
	Sealed by			Cut by		Butted by	
	Overlapped by			Contains		Cut by	
	Cut by					Encloses	
Contemp with	Part of			Part of		Part of	
	Merges with			Includes		Joined with <u>55</u>	
	Includes						
Later than	Above			Cut from		Above	
	Seals			Cuts		Butted to	
	Overlaps					Cuts	
	Lies against					Driven into	
	Contained by					Contained by <u>(7)</u>	
Same as			Characteristically similar to				
E Provisional interpretation							
<p>_____</p> <p>_____</p>							
Note book refs.				Matrix		Phase	Date
F Finds	Pottery			Recorded finds			
	Animal bone						
Samples	Soil	Wood	R/Carbon	Masonry	Brick	Tile	Slag
G Originator(s)				Checked by			Date

Humberside Archaeological Unit

A	Location <i>GATE</i>		Grid ref.		Site code <i>BEG 88</i>		Context/Record no. <i>(74)</i>		
	Category <i>WALL</i>				Form		Orientation		
B	Length		Width <i>1.45m</i>		Diameter		Height/Depth <i>0.70m</i>		
	Co-ordinates				Level				
					T.B.M.=		B.S.= +		
							F.S.= -		
Plan no. <i>7</i>			Section no. <i>19</i>			Photo b/w 11/32-8		Photo c.	
Soil	Colour				Type <i>LIMESTONE WALL</i>				
	Consistence				Inclusions				
Structure	Building materials		Unit sizes		Coursing/Bond				
					Bonding material				
C	Description and comments								
<i>LIMESTONE WALLING FOUR COURSES HIGH, ENCLOSING BEAM (71)</i>									
<i>OVERLYING BEAM 72</i>									
Date encountered			Excavation method			% Level of disturbance			
D	Stratigraphic relationships								
Earlier than	Soil		Cut Feature			Structure			
	Below		Below			Below			
	Sealed by		Cut by			Butted by			
	Overlapped by		Contains			Cut by			
Cut by					Encloses <i>(71)</i>				
Contemp with	Part of		Part of			Part of			
	Merges with		Includes			Joined with			
	Includes								
Later than	Above		Cut from			Above <i>(72)</i>			
	Seals		Cuts			Butted to			
	Overlaps					Cuts			
	Lies against					Driven into			
Contained by					Contained by				
Same as			Characteristically similar to						
E	Provisional interpretation								
Note book refs.				Matrix		Phase		Date	
F	Finds		Recorded finds						
	Pottery								
Animal bone									
Samples	Soil		Wood		R/Carbon		Masonry		
G	Originator(s)				Checked by			Date	

Context/record sheet

A		Location <u>GATE</u>		Grid ref.		Site code <u>BEG 88</u>		Context/Record no. <u>(75)</u>	
		Category <u>TIMBER</u>				Form		Orientation	
B		Length <u>0.40</u>		Width <u>0.28</u>		Diameter		Height/Depth	
		Co-ordinates				Level			
						T.B.M.=		BS.= +	
								FS.= -	
		Plan no.			Section no.			Photo b/w <u>10/9</u>	Photo c.
Soil	Colour				Type				
	Consistence				Inclusions				
Structure	Building materials		Unit sizes		Coursing/Bond				
					Bonding material				
C		Description and comments							
		<u>EASTERN TIMBER POST TIED INTO BEAM (55). BRICKWORK OF (7) BUILT UP AROUND IT. IMMEDIATELY TO THE EAST OF (76)</u>							
Date encountered			Excavation method			% Level of disturbance			
D		Stratigraphic relationships							
		Soil		Cut Feature		Structure			
		Earlier than	Below		Below		Below		
			Sealed by		Cut by		Butted by		
			Overlapped by		Contains		Cut by		
			Cut by				Encloses		
		Contemp with	Part of		Part of		Part of		
			Merges with		Includes		Joined with <u>55</u>		
			Includes						
		Later than	Above		Cut from		Above		
			Seals		Cuts		Butted to		
			Overlaps				Cuts		
			Lies against				Driven into		
Contained by				Contained by					
Same as		Characteristically similar to							
E		Provisional interpretation							
Note book refs.				Matrix		Phase	Date		
F		Pottery			Recorded finds				
		Animal bone							
Samples	Soil	Wood	R/Carbon	Masonry	Brick	Tile	Slag		
G Originator(s)					Checked by			Date	

Humberside Archaeological Unit

A	Location	GATE		Grid ref.	Site code	Context/Record no.		(76)	
	Category	POST SOCKET			Form	Orientation			
B	Length	0.36 m		Width	0.26 m		Diameter	Height/Depth	
	Co-ordinates				Level	T.B.M.=	BS.= +	FS.= -	
	Plan no.	7		Section no.			Photo b/w	10/9	Photo c.
	Soil	Colour				Type			
Consistence					Inclusions				
Structure	Building materials	Unit sizes		Coursing/Bond					
				Bonding material					
C	Description and comments								
ONE OF 2 TIMBER POST-SOCKETS SHOWING IN THE TOP OF (7)									
LIES TO THE WEST OF POST (75), AND IS PRESUMABLY TIED									
INTO THE TOP OF (55)									
Date encountered			Excavation method			% Level of disturbance			
D	Stratigraphic relationships								
Earlier than	Below	Soil			Below	Cut Feature		Below	Structure
	Sealed by				Cut by			Butted by	
	Overlapped by				Contains			Cut by	
	Cut by							Encloses	
Contemp with	Part of				Part of			Part of	
	Merges with				Includes			Joined with	55
	Includes								
Later than	Above				Cut from			Above	
	Seals				Cuts			Butted to	
	Overlaps							Cuts	
	Lies against							Driven into	
Contained by							Contained by		
Same as			Characteristically similar to						
E	Provisional interpretation								
Note book refs.			Matrix			Phase		Date	
F	Finds	Pottery			Recorded finds				
		Animal bone							
Samples	Soil	Wood	R/Carbon	Masonry	Brick	Tile	Slag		
G	Originator(s)				Checked by			Date	

A	Location <i>GATE</i>		Grid ref.		Site code <i>BEG 88</i>		Context/ Record no. <i>(77)</i>		
	Category <i>TIMBER</i>				Form		Orientation		
B	Length <i>0.20</i>		Width <i>0.20</i>		Diameter		Height/Depth <i>0.90m +</i>		
	Co-ordinates				Level				
					T.B.M.=		B.S.= +		
					F.S.= -				
C	Plan no.		Section no.		Photo b/w <i>6/42</i>		Photo c.		
	Soil	Colour			Type <i>OAK</i> <i>10/34-8</i> <i>7/3-4, 7/37-40</i>				
		Consistence			Inclusions				
	Structure	Building materials		Unit sizes		Coursing/Bond			
				Bonding material					
Description and comments									
<i>UPRIGHT TIMBER SEALED BENEATH (66) (7) - SOUTHERN ARM OF BARRICAN BRICKWORK.</i>									
Date encountered			Excavation method			% Level of disturbance			
D	Stratigraphic relationships								
	Earlier than	Soil			Cut Feature			Structure	
		Below				Below			Below <i>(66) (7)</i>
		Sealed by				Cut by			Butted by
		Overlapped by				Contains			Cut by
	Contemp with							Encloses	
		Part of				Part of			Part of
		Merges with				Includes			Joined with
	Later than								
		Includes							
		Above				Cut from			Above
		Seals				Cuts			Butted to
		Overlaps							Cuts
								Driven into	
								Contained by	
Same as			Characteristically similar to						
E Provisional interpretation									
Note book refs.			Matrix		Phase		Date		
F	Finds		Recorded finds						
	Pottery								
Animal bone									
Samples	Soil	Wood	R/Carbon	Masonry	Brick	Tile	Slag	<i>DENDRO</i>	
								✓	
G Originator(s)					Checked by		Date		

A	Location <u>GATE</u>		Grid ref.		Site code <u>BEG 88</u>		Context/Record no. <u>78</u>				
	Category <u>STRUCTURE</u>				Form		Orientation				
B	Length		Width		Diameter		Height/Depth				
	Co-ordinates				Level						
	: : :				T.B.M.=		B.S.= + F.S.= -				
	Plan no.		Section no.		Photo b/w 11/28-43		Photo c.				
Soil	Colour				Type <u>LIMESTONE</u>						
	Consistence				Inclusions						
Structure	Building materials		Unit sizes		Coursing/Bond						
					Bonding material						
C	Description and comments										
<u>LIMESTONE FOOTINGS UNDER BRICKWORK (7) OF NORTHWALL BARBICAN</u>											
<u>(SEE CONTEXT (7))</u>											
Date encountered			Excavation method			% Level of disturbance					
D	Stratigraphic relationships										
Earlier than	Soil		Cut Feature			Structure					
	Below <u>7</u>		Below			Below					
	Sealed by		Cut by			Butted by					
	Overlapped by		Contains			Cut by					
Contemp with	Part of		Part of			Part of					
	Merges with		Includes			Joined with					
	Includes										
Later than	Above		Cut from			Above					
	Seals		Cuts			Butted to					
	Overlaps					Cuts					
	Lies against					Driven into					
Contained by					Contained by						
Same as			Characteristically similar to								
E	Provisional interpretation										
Note book refs.				Matrix		Phase		Date			
F	Finds		Recorded finds								
	Pottery										
Animal bone											
Samples	Soil		Wood		R/Carbon		Masonry		Brick		
									Tile		
								Slag			
G	Originator(s)				Checked by			Date			

A	Location <u>GATE</u>		Grid ref.		Site code <u>BEG 88</u>		Context/Record no. <u>79</u>		
	Category <u>STRUCTURE</u>				Form		Orientation		
B	Length		Width		Diameter		Height/Depth		
	Co-ordinates				Level				
					T.B.M.=		B.S.= +		
							F.S.= -		
C	Plan no.		Section no.			Photo b/w		Photo c.	
	Soil	Colour			Type <u>LIMESTONE</u>				
		Consistence			Inclusions				
	Structure	Building materials		Unit sizes		Coursing/Bond			
				Bonding material					
Description and comments									
<u>LIMESTONE FOOTINGS BELOW (65) TO NORTH OF NORTHERN ARM OF BARRICADE</u>									
Date encountered			Excavation method			% Level of disturbance			
D	Stratigraphic relationships								
			Soil		Cut Feature		Structure		
	Earlier than	Below		Below		Below			
		Sealed by		Cut by		Butted by			
		Overlapped by		Contains		Cut by			
		Cut by				Encloses			
	Contemp with	Part of		Part of		Part of			
		Merges with		Includes		Joined with			
		Includes							
	Later than	Above		Cut from		Above			
		Seals		Cuts		Butted to			
		Overlaps				Cuts			
		Lies against				Driven into			
Contained by						Contained by			
Same as			Characteristically similar to						
E Provisional interpretation									
Note book refs.					Matrix		Phase	Date	
F	Finds	Pottery			Recorded finds				
		Animal bone							
Samples	Soil		Wood	R/Carbon	Masonry	Brick	Tile	Slag	
G Originator(s)					Checked by			Date	

BEG 88

(66)

Southern arm of barbiian brickwork. Bricks 26×13 — 27×14 mm.
Slightly stepped foundations at base, overlying a wooden sole plate (65)
The bottom four courses of brickwork simply about the main body of the
brickwork. Above this, the bricks are bonded into the main fabric with alternate
courses of projecting headers.

BEG 88

(67)

Black gritty loam sealing wall (26) Depth 8cm
Diameter uncertain.
Underneath (17)