

Figure 2.52: Old House Cone composite 1995 + 2002 - Figure 2A from 2002 report

It should be noted that the grid references shown on Figure 2.52 are not accurate. This is not reflected in the positioning of the excavated area in Figures 2.54, 2.55, 2.56 and 2.57 below. These show the cone foundation in the position corresponding to that from the 1870 plan and also as confirmed by the 1995 excavation



As the recording was being completed, so there was encroachment on the site, and the final destruction of the Old House Cone was photographed before the archaeologists had left site (Figure 2.53.)

Figure 2.53: Old House Cone - Final destruction, 2002




Figure 2.54: 2002 salvage/watching brief recording on site-centred map.