



Plate 1: Exterior, North Elevation, from the north



Plate 2: Exterior, North, and West elevation, from the north west



Plate 3: Exterior, main building South elevation and extension West elevation, from the south west



Plate 4: Exterior, extension West elevation roof join, from the west



Plate 5: Exterior, South elevation, from the south east



Plate 6: Exterior, Exterior, South elevation - East of main extension, from the south



Plate 7: Exterior, North elevation detail of East quoin, from the north



Plate 8: Exterior, North elevation detail of West quoin, from the north



Plate 9: Exterior, North elevation detail of door 013, from the north



Plate 10: Exterior, West gable elevation - lower, from the west



Plate 11: Exterior, West gable elevation - upper, from the west



Plate 12: Exterior, West elevation showing South wall, from the south west



Plate 13: Exterior, Western side of South elevation, from the south



Plate 14: Exterior, South elevation detail shot of window 008, from the south



Plate 15: Exterior, South elevation, from the south



Plate 16: Exterior, East elevation extension roof, from the south east





Plate 17: Exterior, East elevation - South end, from the east



Plate 18: Ground floor interior, Room 0/3, detail of exposed stone on North wall, from south



Plate 19: Ground floor interior, Room 0/1, general shot of room, from the north



Plate 20: Ground floor interior, Room 0/1, general shot of the room, from the south



Plate 21: Ground floor interior, Room 0/1, detail of window 001, from the north



Plate 22: Ground floor interior, Room 0/1, detail of boiler cupboard, from the west



Plate 23: Ground floor interior, Room 0/1, detail of open floorboard, from the west



Plate 24: Ground floor interior, Room 0/1, detail of step taken from door 007, from the north



Plate 25: Ground floor interior, Room 0/1, room showing room 0/2 entry with ceiling detail, from the west



Plate 26: Ground floor interior, Room 0/2, detail of window 005, from the north east



Plate 27: Ground floor interior, Room 0/2, detail of East wall, from the west



Plate 28: Ground floor interior, Room 0/3, North wall, from the south



Plate 29: Ground floor interior, Room 0/3, detail of fireplace 009, from the west



Plate 30: Ground floor interior, Room 0/3, detail of collapsed fireplace surround 006, from the west



Plate 31: Ground floor interior, Room 0/3, detail of window 010, from the south



Plate 32: Ground floor interior, Room 0/3, detail of window 008, from the north





Plate 33: Ground floor interior, Room 0/3, West wall, from the east




Plate 34: Ground floor interior, Room 0/4, detail of door 013, from the south east



Plate 35: Ground floor interior, Room 0/4, detail of door 013 - base, from the south



Plate 36: Ground floor interior, Room 0/4, East wall, and door 011, from the west



Plate 37: Ground floor interior, Room 0/6, South Wall, from the north



Plate 38: Ground floor interior, Room 05, detail of window 016, from the north



Plate 39: Ground floor interior, Room 0/5, access hatch, from the south



Plate 40: Ground floor interior, Room 0/5, North wall, from the south



Plate 41: Ground floor interior, Room 0/7, detail of window 017, from the north



Plate 42: Ground floor interior, Room 0/7, detail of window 019, from the south



Plate 43: Ground floor interior, Room 0/7, detail of window 017 recess showing metal, from the north




Plate 44: Ground floor interior, Room 0/7, detail of hole in Western edge of window 017 recess - inside cavity, from the west



Plate 45: Ground floor interior, Room 0/7, detail of fireplace 018, from the east