

THE FOX INN Willian, Herts

HN508

Archaeological Monitoring Report



THE HERITAGE NETWORK LTD

Registered with the Institute of Field Archaeologists as an Archaeological Organisation
Archaeological Director: David Hillelson, BA MIFA

THE FOX INN Willian, Herts.

HN508

Archaeological Monitoring Report

Prepared on behalf of Anglia County Inns Ltd

by

David Kaye, BA, PIFA

Report no. 293

May 2005

© The Heritage Network Ltd

Contents

	Summary	Page i
Section 1	Introduction	
Section 2	Fieldwork	Page 2
Section 3		
Section 4	Schedule of Site Visits	Page 5
Section 5	Bibliography	Page 5
	Illustrations	

Acknowledgements

The fieldwork for this project was carried out by David Kaye, Karin Semmelmann and Geoff Saunders under the supervision of Chris Turner. The report text and illustrations were prepared by David Kaye. The report was edited by David Hillelson.

The Heritage Network would like to express its thanks to Richard Hodson Survey and Technical Services; Cliff Nye, Anglia County Inns Ltd., and the staff of the County Archaeology Office, Hertfordshire County Council for their cooperation and assistance in the execution of this project.

Summary

Site name and address:	The Fox Inn, Willian, Hertfordshire			
County:	Hertfordshire	District:	North Herts.	
Village/town:	Willian	Parish:	Letchworth	
Planning reference:	01/04/1305	NGR:	TL 2241 3069	
Client name and address:	Anglia County Inns Ltd., The Fox Inn, Willian, LETCHWORTH, SG6 2AE			
Nature of work:	Extension	Present land use:	Car park and garden	
Size of affected area:	$c.130m^2$	Size of area investigated:	$c.130m^2$	
Site Code:	HN508	Other reference:	n/a	
Organisation:	Heritage Network	Site Director:	David Hillelson	
Type of work:	Monitoring	Archive location:	North Herts Museums	
Start of work	17/01/2005	Finish of work	03/02/2005	
Related SMR Nos:	n/a	Periods represented:	None	
Previous summaries/reports:	n/a			

Synopsis: In response to a condition on the planning permission for an extension at The Fox Inn, Willian, Herts., the Heritage Network was commissioned by Richard Hodson Survey and Technical Services on behalf of the owner Anglia County Inns Ltd to undertake the archaeological monitoring of the development groundworks.

Despite the proximity of the study area to the 12th century church and being within the *Area of Archaeological Significance no.99* (AAS99), which defines the medieval settlement of Willian in the District Local Plan, no significant archaeological features were encountered on the site. No artefacts were recovered from the spoil.

HN508/report

1. Introduction

- 1.1 This report has been prepared on behalf of Anglia County Inns Ltd as part of a programme of monitoring and recording the groundworks for an extension to The Fox Inn, Willian, Hertfordshire. The planning permission for the development (ref. 01/04/1305), granted by the North Herts. District Council (NHDC), was subject to a standard archaeological condition, in accordance with the provisions of the Department of the Environment's Planning Policy Guidance Note 16 (PPG16). The scope of the required work followed the Design Brief for Archaeological Monitoring and Recording issued by the County Archaeology Office (CAO) of Hertfordshire County Council, acting as advisers to NHDC. A full specification of the work was contained in the Heritage Network's approved Project Design, dated July 2004.
- 1.2 The site, centred on NGR TL 2241 3069, is located on the south side of Baldock Lane, just to the north-west of the parish church of All Saints. The development proposes an extension to the southern elevation of the existing building (see Figure 1).
- 1.3 The site lies within Area of Archaeological Significance no.99 (AAS99), which defines the medieval settlement of Willian in the District Local Plan. Willian is recorded in the Domesday Book and the parish church dates from the 12th century.
- 1.4 The aim of the present project has been to identify and record any archaeological features and deposits which were uncovered; and to retrieve artefactual and ecofactual elements which would allow the date, character, and significance of the site to be assessed in accordance with current regional research agenda (Brown and Glazebrook, 2000), and subject to the limitations of reasonable safety and practicality.
- 1.5 The present report describes the findings of the monitoring programme and is intended to complete the requirements of the planning condition.

HN508/report Page 1

2. Fieldwork

TOPOGRAPHY AND GEOLOGY

2.1 The site lies to the south side of Baldock Lane, just to the north-west of the parish church of All Saints. The geology was consistent across the site and comprised a layer of very dark brown silty clay topsoil approximately 0.4m thick beneath which was a lighter brown slightly sandier subsoil 0.4m thick over the yellow sand natural.

METHODOLOGY

- 2.2 The timetable for the fieldwork followed the client's groundwork schedule. A number of site visits were made to supervise the excavation of the footings and drainage trenches and a soakaway.
- 2.3 The machining was undertaken using a tracked mini-digger fitted with a 450mm toothed and an 800mm toothless bucket, as required.
- 2.4 Spoil from the various stages of the groundworks was inspected for archaeological artefacts.
- 2.5 The project has been carried out in accordance with the requirements of the Design Brief, and with the Heritage Network's approved Project Design.

MONITORING AND RECORDING

Footings trenches

- 2.6 The footings trenches for the new extension measured approximately 0.45m in width and varied from 1.0m in depth to approximately 1.9m in the eastern corner where some subsidence had taken place (Figure 2).
 - 2.7 No archaeological features or artefacts were revealed.

Drainage trenches

2.8 The drainage trenches leading to the soakaway were of such a depth that they did not cut through the substantial overburden in the car park to the south-east of the existing building.

Soakaway

- 2.9 A single soakaway, measuring approximately 2.5m square by 2.5m deep, was excavated on the south-east of the new extension (Figure 2).
- **2.10** At a depth of approximately 1.1m in the north-west facing section of the soakaway 4 brick courses were observed indicating the base of a wall of post medieval date.

HN508/report Page 2

3. Discussion and conclusion

3.1 Despite the site's location within an area of known archaeological activity, the monitoring of the groundworks associated with the new extension failed to reveal any features other than the base of the post medieval wall in the soakaway. No artefacts from the medieval or any other period were recovered.

Conclusion

3.2 Despite the proximity of the site to the 12th century church, and its location in the area defining medieval William no archaeology was observed during the monitoring process.

Confidence Rating

3.3 The conditions were generally acceptable for the identification of potential features and deposits, and for their investigation. There were no circumstances which would lead to a confidence rating for the work which was less than High.

4. Schedule of site visits

Date	Staff	Hours	Comments
17/01/05	DGK	7	Inspection of footings trenches
19/01/05	DGK	1	Inspection of footings trenches
20/01/05	DGK	1	Inspection of footings trenches
01/02/05	DGK	1	Inspection of drainage trenches
03/02/05	DGK	1	Inspection of soakaway

5. Bibliography

Hillelson, D. 2004, *The Fox Inn, Willian, Herts: Archaeological Project Design*. Heritage Network

6. Illustrations


Figure 1	Site location
Figure 2	Site layou


HN508/report Page 3



The Fox Inn, Willian, Herts

HN508








Site Location

Reproduced from OS mapping with the permission of the controller of Her Majesty's Stationery Office, Licence no.AL100014861

Scale 1:500

Figure 1



Site Layout

Scale 1:300

Figure 2