




Pl. 1 General view of trenching. Looking north.



Pl. 2 General view of trenching behind barn. Looking north.




Pl. 3 General view of first-floor room. Looking north.




Pl. 4 Top of exposed cross-beam and joists in first-floor room. Looking east.





Pl. 5 Detail of the joists showing the carpenter's marks. Looking west. 0.25m scale.



Pl. 6 Detail of the mortise tenon fixed to earlier joist. Looking east. 0.25m scale.