
CONTENTS

	<i>Page</i>
1 INTRODUCTION.....	1
2 SITE LOCATION.....	3
3 AIMS AND METHODOLOGY.....	8
4 PREVIOUS WORK.....	8
5 HISTORICAL CONTEXT.....	9
6 RESULTS.....	12
7 CONCLUSION.....	37
8 BIBLIOGRAPHY.....	38
9 APPENDIX.....	39

LIST OF FIGURES

		<i>Page</i>
Figure 1	Site Location	2
Figure 2	First Edition OS map 1861 (6 inch to 1 mile)	4
Figure 3	First Edition OS map c.1865 (25" to 1 mile)	5
Figure 4	Second Edition OS map 1901 (25" to 1 mile)	6
Figure 5	Site location (1:2500 1967 edition)	7
Figure 6	Hodgkinson and Donald map of 1774 (surveyed 1770)	10
Figure 7	Tithe map 1843	11
Figure 8	Site plan	12
Figure 9	South facing elevation of Building 'A'	14
Figure 10	Northern elevation of Building A	18
Figure 11	Eastern gable end of Building A and east elevation of Building B	19
Figure 12	Western elevation of Building B and gable end of Building A	22
Figure 13	Ground plan	24
Figure 14	First floor plan	29

LIST OF PLATES

		<i>Page</i>
Plate 1	South facing elevation of Building 'A'	13
Plate 2	Western gable of Building A, date stone and window	15
Plate 3	Detail of date stone '1887'	15
Plate 4	Southern elevation of Building A, cart doorways	16
Plate 5	Detail of ventilation slit	16
Plate 6	Northern elevation of Building A	17
Plate 7	Eastern gable end of Building A	20
Plate 8	Western elevation of Building B	21
Plate 9	Location of construction break, Building B	21
Plate 10	Southern gable end of Building B	23
Plate 11	Timber stall divider, lean-to at west end of range (Building A)	25
Plate 12	Interior of byre, Building A	25
Plate 13	Wooden stairs to hayloft, cart shed in Building A	27
Plate 14	Interior of cart shed, Building A	27
Plate 15	Eastern-most room in Building A	28
Plate 16	Masonry gable wall, first floor of Building A	30
Plate 17	Detail of roof structure, first floor of Building A	30
Plate 18	Detail of gabled dormer with pitching door	31
Plate 19	First floor window, northern gable end of Building A	31
Plate 20	Stone stairs, Building B	33
Plate 21	Hayrack, ground floor of Building B	33
Plate 22	Roof structure, Building B	34

LIST OF PLATES

		<i>Page</i>
Plate 23	First floor window, western elevation of Building B	34
Plate 24	Northern elevation of farmhouse	35
Plate 25	Brick-built building, western side of site	36
Plate 26	Stone-built shed on west side of track into farm	36

PHOTOGRAPHS ON CD-ROM

- 1 Farm buildings from the east
- 2 Farmhouse and farm buildings from east
- 3 Farm buildings from the east
- 4 Farm buildings from the east
- 5 Farm buildings from north-east
- 6 Farm buildings from north-east
- 7 South elevation of Building A
- 8 South elevation of Building A
- 9 South elevation of Building A
- 10 South elevation of Building A
- 11 South elevation of Building A
- 12 South elevation of Building A
- 13 Arched cart doorways – South elevation of Building A
- 14 Arched cart doorways – South elevation of Building A
- 15 Arched cart doorway
- 16 South elevation of Building A
- 17 West elevation of Building B
- 18 West elevation of Building B
- 19 West elevation of Building B
- 20 Large doorway – Western elevation of Building B
- 21 South elevation of Building B
- 22 South elevation of Building B

PHOTOGRAPHS ON CD-ROM

- 23 Farm buildings from the south-east
- 24 East elevation of Building B
- 25 Farmhouse and farm buildings from the east
- 26 East elevation of Building B
- 27 East elevation of Building B
- 28 East elevation of Building B
- 29 Eastern gable end of Building A
- 30 Eastern gable end of Building A
- 31 Eastern gable end of Building A
- 32 Farm buildings from the north-east
- 33 Farm buildings from the north-east
- 34 Modern shed – east side of farm
- 35 Northern elevation of Building A
- 36 Northern elevation of Building A
- 37 Northern elevation of Building A
- 38 Northern elevation of Building A
- 39 Northern elevation of Building A
- 40 Northern elevation of Building A
- 41 Northern elevation of lean-to
- 42 West elevation of lean-to and Building A
- 43 West elevation of lean-to and Building A
- 44 Window and date stone – west elevation of Building A
- 45 Detail of date stone ‘1887’

PHOTOGRAPHS ON CD-ROM

- 46 Detail of byre doorway – north elevation of Building A
- 47 Detail of byre doorway – north elevation of Building A
- 48 Detail of tooling – byre doorway, Building A
- 49 Eastern elevation of Buildings A and B
- 50 Detail of ventilation slit
- 51 Detail of dressed stonework – doorway West elevation of Building B
- 52 First floor window – west elevation of Building B
- 53 Interior of lean-to
- 54 Timber division – interior of lean-to
- 55 Interior of byre – Building A
- 56 Interior of byre – Building A
- 57 Doorway between byres – Building A
- 58 Interior of byre – Building A
- 59 Interior of byre – Building A
- 60 Interior of byre – Building A
- 61 Interior of byre – Building A
- 62 Interior of byre – Building A
- 63 Interior of byre – Building A
- 64 Doorway between cart shed and byre – Building A
- 65 Wooden stairs – Building A
- 66 Doorway and wooden stairs – Building A
- 67 Interior of large doorway – Building A

PHOTOGRAPHS ON CD-ROM

- 68 Interior of large doorway – building A
- 69 Detail of door handle – Building A
- 70 Internal doorway – Building A
- 71 View of upper floor – Building A
- 72 First floor – Building A looking west
- 73 Roof detail – Building A
- 74 Pitching door – Building A
- 75 Detail of ventilation slit
- 76 Interior of Building B looking east
- 77 Arched stonework – Building A
- 78 Detail of pitching door – Building A
- 79 Roof detail – Building A
- 80 Roof detail – Building A
- 81 Raised floor – first floor of Building A
- 82 Detail of pitching door – Building A
- 83 Doorway – first floor of Building A
- 84 Hatch in floor – Building A
- 85 Doorway – first floor
- 86 Window – first floor east end of Building A
- 87 Roof detail – join between Building A and B
- 88 Interior of room – east end of Building A
- 89 Hatch – floor of eastern room – Building A
- 90 Owl hole – Building B

PHOTOGRAPHS ON CD-ROM

- 91 Detail of door handle
- 92 First floor of barn – Building B
- 93 First floor of barn – Building B
- 94 Interior view of large doorway – Building B
- 95 Roof detail – Building B
- 96 Stone stairs – Building B
- 97 Stone stairs – Building B
- 98 Interior view of winnowing door – Building B
- 99 Interior view of winnowing door – Building B
- 100 Stone stairs – Building B
- 101 Interior of Building A looking west
- 102 First floor doorway between Buildings A and B
- 103 Roof detail – Building A
- 104 Interior of byre – Building A
- 105 Interior of byre – Building A
- 106 Interior of byre – Building A
- 107 Interior of byre – Building A
- 108 Interior of byre – Building A
- 109 Interior of byre – Building A
- 110 Interior of byre – east end of Building A
- 111 Interior view of doorway – east end of Building A
- 112 Interior view of doorway – east end of Building A
- 113 Row of square blocks of masonry – Building A

PHOTOGRAPHS ON CD-ROM

- 114 Door to lean-to – north elevation of Building A
- 115 Interior of lean-to (northern side)
- 116 Interior of lean-to (east side)
- 117 Interior of room – northern end of Building B
- 118 Hayrack – room at northern end of Building B
- 119 Interior of room – northern end of Building B
- 120 Interior of room – northern end of Building B
- 121 Tithe map of 1843

NON-TECHNICAL SUMMARY

North Pennines Archaeology Ltd were commissioned by Alpha Design to undertake a building recording project at Low Allenwood Farm, Broadwath, Carlisle in December 2005 prior to the redevelopment of a complex of agricultural buildings. The survey revealed that Low Allenwood Farm was in existence by 1843 and is likely to date back to the enclosure of this area in the late 18th century. Much of the complex recorded during this survey date to a late 19th century redevelopment of the site and were subject to later alterations in the 20th century in line with changing agricultural practises.

ACKNOWLEDGEMENTS

This report was produced by Fiona Wooler and edited by Juliet Reeves and Matthew Town. We would like to thank the invaluable assistance given by Stephen White, Local Studies, Carlisle Library and Denis Perriam during the completion of this report.