


 <p>North Pennines Archaeology Ltd 2007</p>	<p>PROJECT: Market Dock North Watching Brief</p> <p>SCALE: 1:600</p> <p>REPORT No: CP 548/07</p> <p>CLIENT: Mandale Commercial Limited</p> <p>DRAWN BY: CP</p> <p>DATE: September 2007</p>	<p>LOCATION:</p> 	<p>KEY:</p> <ul style="list-style-type: none">  Excavated Area  Archaeological Feature (concrete)  Archaeological Feature (timber)
--	--	---	--

Figure 6: Location of Features Encountered During Watching Brief