


**BUILDING SURVEY OF BARNs AT CROSSHOLME FARM,
WELL STREET, BISHOP NORTON, LINCOLNSHIRE**

NGR: SK 9863 9215
Planning ref: M03/P/1003
Accession number: 2007.245
Site Code: BINC 07



Report prepared for
Claystone Developments Ltd.

by Phil Chavasse and Chris Clay
December 2007

Allen Archaeological Associates
Unit 1c, Branston Business Park
Lincoln Road
Branston
LN4 1NT
Tel.: 01522 794400
E-mail: allenarchaeology@btconnect.com
www.allenarchaeology.co.uk



Contents

1.0	Introduction	2
2.0	Site location and description	2
3.0	Planning background	2
4.0	Methodology	3
5.0	Results	3
5.1	North range	3
5.2	East range	5
5.3	Building 6	6
6.0	Discussion and conclusion	6
7.0	Acknowledgements	6
8.0	References	6
9.0	The Plates	8
	Appendix 1: Photographic archive list	16

List of Figures

- Figure 1:** Site location at scale 1:25,000
Figure 2: Site location plan at scale 1:500, with the development area outlined in red
Figure 3: Location and direction of photographs taken on ground floor. (Scale 1:250)
Figure 4: Location and direction of photographs on the first floor. (Scale 1:250)
Figure 5: Elevation drawings of Buildings 1 to 3 at scale 1:250
Figure 6: Elevation drawings of Buildings 4 to 6, scale 1:250

List of Plates

- Plate 1:** The north range of buildings, and the covered crew yard, looking south-east.
Plate 2: The north range of buildings, looking south-east from the west end of Building 1.
Plate 3: Stable block 1b, on the southern elevation of building 1. Looking north-north-east.
Plate 4: North elevation of Building 2, showing exposed rubble core and blocked doorway. Looking south.
Plate 5: South elevation of Building 2, showing the window and part of the entrance to the west. The saw tooth brickwork is likely to be an original feature.
Plate 6: North elevation of Building 3, looking south-east.
Plate 7: East end of Building 3, showing the wooden hayloft. Looking east.
Plate 8: Brick partition wall in Building 3, looking west.
Plate 9: Doors in south elevation of Building 3, looking north-east.
Plate 10: North elevation of Building 3, east end. Note the blocked doorway defined by the saw tooth brickwork with smaller door inserted. The window to the west truncates a ventilation slit. Looking south.
Plate 11: Loading hatch in north wall of Building 3, and breeze block storage bay. The chute in the middle of the breeze block wall allows grain to poured into sacks on the ground floor. Looking north-west.
Plate 12: East range of the barn complex looking west-south-west. Building 4 is in the foreground, and largely obscured by ivy, with Building 5 to the left of the shot in the background.
Plate 13: South elevation of cattle shed 4a, looking north-north-west. The eastern gable end of Building 3 is visible at the left of the shot.
Plate 14: East range of the barn complex, with Buildings 4 and 5 in the middle distance and Building 3 in the background. Looking north-north-west.
Plate 15: West elevation of stable block 4b, looking east.
Plate 16: Brick feeding trough in stable block 4b, looking north.
Plate 17: West elevation of garage 5a and stable 5b, looking east-north-east.
Plate 18: North elevation of building 5b, abutted by garage 5a. Looking south-south-east.
Plate 19: South elevation of building 5b, and adjacent yard 5c. Looking north-east.
Plate 20: South elevation of building 6a, looking north-north-west.
Plate 21: Cart shed 6b, north elevation, looking south-south-east.
Plate 22: West elevation of building 6b, looking east.
Plate 23: The barns from the west, showing building 6b in the foreground, with the covered crew yard and building 1 in the background.
Plate 24: View along south boundary of covered crew yard, looking east-north-east.