Shot No	Facing	Туре	Description
		floor/detail	
42	E	Interior/ground floor/detail	Detail of windmill graffiti
43	NE	Interior/ground floor	Interior of cog house towards north elevation
44	E	Interior/ground floor	Interior of cog house showing stone nut and flour chute
45	E	Interior/ground floor	Interior of cog house showing stone nut and flour chute
46	SE	Interior/below ground floor	Interior of cog house showing stone nut
47	N	Interior/below ground floor/detail	Detail of central shaft connecting to water wheel
48	N	Interior/below ground floor	Wallower above pit wheel
49	N	Interior/below ground floor	Wallower above pit wheel
50	NNE	Interior/ground floor	East elevation and east partition of cog house
51	N	Interior/ground floor	North elevation of cog house and stone nut
52	NW	Interior/1 <sup>st</sup> floor	General interior shot
53	ENE	Interior/1 <sup>st</sup> floor	North and east elevation and grinding mechanisms
54	ENE	Interior/1 <sup>st</sup> floor/detail	Detail of crown wheel and belt wheel
55	N	Interior/1 <sup>st</sup> floor/detail	Detail of crown wheel, millstones and sack hoist wheel
56	SE	Interior/1 <sup>st</sup> floor	East and south elevation with staircase in the corner
57	SW	Interior/1 <sup>st</sup> floor	South and west elevation
58	W	Interior/2 <sup>nd</sup> floor/detail	Roof structure
59	E	Interior/2 <sup>nd</sup> floor/detail	Roof structure
60	ESE	Interior/2 <sup>nd</sup> floor/detail	Wooden pulley mechanism
61	S	Interior/2 <sup>nd</sup> floor/detail	Wooden pulley mechanism
62	NE	Interior/2 <sup>nd</sup> floor/detail	North and east elevation and wooden winch mechanism
63	ESE	Interior/2 <sup>nd</sup> floor/detail	East elevation and wooden winch mechanism
64	SSE	Interior/2 <sup>nd</sup> floor	South elevation and ephemera
65	S	Interior/2 <sup>nd</sup> floor/detail	Detail of void in roof
66	W	Interior/2 <sup>nd</sup> floor	East elevation and window
67	S	Interior/2 <sup>nd</sup>	Staircase leading from 2 <sup>nd</sup> to 1 <sup>st</sup> floor
68	S	Interior/2 <sup>nd</sup> floor/detail	Close-up of exposed limestone where plaster has fallen off
69	S	Interior/1 <sup>st</sup> floor/detail	Plaster with graffiti on south elevation
70	S	Interior/1 <sup>st</sup> floor/detail	Close-up of graffiti "TH 1827"
71	S	Interior/1 <sup>st</sup> floor/detail	Close-up of graffiti "R W"

Shot No	Facing	Туре	Description
72	S	Interior/1 <sup>st</sup>	Close-up of graffiti "I W" 1807
		floor/detail	
73	S	Interior/1 <sup>st</sup>	Close-up of graffiti "W", "Sept"
		floor/detail	
74	S	Interior/1 <sup>st</sup>	Close-up of graffiti "W", "Sept 26? 1807"
		floor/detail	
75	S	Interior/1 <sup>st</sup>	Close-up of group of graffiti
		floor/detail	
76	S	Ground	Symmetrical flower graffiti on south internal elevation near to
		floor/detail	doors
77	NW	Exterior	General shot of the miller's lodge and mill within its landscape






Figure 1: Site location at scale 1:25,000, with the site in red © Crown Copyright 2006. All rights reserved. Licence Number 100047330





Ν

**Figure 3:** Plan showing location and orientation of photographs taken on ground floor at scale 1:50 (Survey drawings provided by Scorer and Hawkins)








Figure 4: Plan showing location and orientation of photographs taken on first floor at scale 1:50 (Survey drawings provided by Scorer and Hawkins)





**Figure 5:** Plan showing location and orientation of photographs taken on second floor at scale 1:50 (Survey drawings provided by Scorer and Hawkins)

























**Figure 8:** Schematic diagram of ancillary machinery for flour dresser and sack hoist, looking north (not to scale). For diagram of machinery below see Figure 7.








Figure 10: 1902 Ordnance Survey map with the site outlined in red. Not to scale

