

Butlers Farm, Broomfield, Essex.



Building 5. This is a modern Atcost precast concrete framed Dutch barn originally open through to the adjoining building. Now with a bale wall.



Building 7. Another precast concrete framed storage building. Lower block walls with asbestos cladding above.



Inside it shows the large area used for bulk grain storage. The gable wall adjacent to the barn has block-work to eaves as it would be impossible to attach the cladding.



The east wall has the lower height of blockwork as to the south. These walls had been cloth lined as the earlier lined buildings on the site which it replaced.



A general view of the farmyard as it would be seen from the main road. The carriage shed, Building 3 to the left with the stable range building 4 framing the road boundary and showing differences in the walling.



The view of the farmyard from southwest in the Chelmer valley shows other buildings with building 2 in the foreground. The barn and later buildings behind.