

Stone Hall Barn, Matching, Essex.



From survey digitals, LUH02, this view of the south west corner of the barn shows the lean-to extension, the projecting gable to the midstre with brackets and the primary braced wall structure to the barn.



L23 shows the typical wall structure of the northerly aisle, set onto a good brick plinth the lower bricks of which are early but the top courses are later showing that a sill change has taken place.