

Stone Hall Barn, Matching, Essex.



13 is scarf number I from the west in the aisle walling. Face halved and bladed type. Chiselled I.



16 - Carpenters assembly marks chiselled as are all to the construction. This where stud meets brace.



17 - marks where wall brace meets upper part of stud on aisle wall.



15 - more examples of assembly marks IIII where stud meets brace.



12 - reused timber in sill at western end of aisle is moulded and has mortises for meeting timbers. Suggest from a large window or panelled ceiling.