

Stone Hall Barn, Matching, Essex.



33 shows the plinth towards the northern end with early brick and later on edge brick under sill.



37 shows the plinth towards the western end where the barn has been reduced and this is C19 brickwork.