

Enlarged and lined-in extract from the 1840 Tithe map for Matching.

The barn is shown clearly within the farmyard with possibly another barn below it against the road and the block to the left possibly contains the remaining stable with the house below it. The area to the right of the midstrey may be a previous attachment but the barn does suggest the lean-to is extant at that time to the left of the midstrey.