

Shenfield Hall Barn, Shenfield, Essex.



Extract from 1920 RC photograph showing barn with the two bays now removed at the south. A lean-to also existed for at least one of the bays. Also note that stable doors had already been inserted into the bays of the barn to the north of the older section of the barn.



The barn in 2007. Note the doors to the north midstrey have been reduced in height. The northern stable door is similar but with a glass light above. The other door has changed completely and a window has been added between it and the south midstrey, now devoid of doors.



The barn in 2007 viewed from the north-east. The building has lost buildings from this corner in the period since 1937.