

Shenfield Hall Barn, Shenfield, Essex.



(287) South open truss showing late twentieth century infill when bays removed and structural elements possibly from the fifteenth century



(290) West wall (rebuilt) and roof bay 1-2



(297) Fifteenth century scarf joint



(298) Rebuild scarf seventeenth century.