




(277) Long view from south in bay 7-8 to infill on trusses 4 end of seventeenth century rebuild and truss 2 closing off bay 1-2



(266) Roof form in eighteenth century bay 6-7 east with simple clasped purlin roof



(267) Aisle wall structure bay 6-7. Truss 7 (left) was end this build