Shenfield Hall Barn, Shenfield, Essex.



(255) Bay 5-6 east showing framing for opposing door to porch in eighteenth century build. Note that the primary bracing to the wall frame runs through to the next bay, The aisle wall frames do not relate to the main trusses but are built as independent units

(256) Elm board infill to aisle wall. Top board was outer board of tree and axe converted before through sawing the other boards.

Note stepped mortise entry for security bar for the eighteenth doors originally in this opening.

Ρ5