

Shenfield Hall Barn, Shenfield, Essex.



(241) View to post 3D the intermediate of the seventeenth century rebuild. note the face halved bladed scarf to the arcade plate.



(238) Bay 2-3 to the east showing aisle wall framing for seventeenth century rebuild. note the arch bracing to the outer walls



(248) View from aisle to post 3D showing in previous use had aisle shores.