

**Shenfield Hall Barn, Shenfield, Essex.**



(143) Typical face halved scarf to arcade plates other than in bay 1-2.



(144) Aisle plate bladed scarfs similar to arcade plates but shorter.



(146) Aisle arch bracing to the bays of the seventeenth century rebuild.



(145) One of two good cast iron windows circa. mid nineteenth century with opening vent.



(67) Carved jowl to post 6D of eighteenth century build with initials J + C 1757. 68 shows moulded detail on arcade post.



(68)