

Shenfield Hall Barn, Shenfield, Essex.



(189) View into north porch roof. (169) View up into hip of north porch with opening infill.



(178) Top of original door opening with line of pegs to support pigeon boxes.



(177) Detail of side showing support pegs and end bar for pigeon boxes with late infill above.



(176) Detail of shaped support peg for the boxes.