

Feeringbury Barn, Feering, Essex.



Photo 1. Front of barn from the north east. At least one grain silo may remain.



Photo 2. Stable range from the north east. Note walls removed to make implement shed.



Photo 30. View of the barn from the east where the end wall has all late infill and boarding. Note flap in small door at the side.