

Feeringbury Barn, Feering, Essex.



Photo 54. Typical detail to top of jowled arcade post with halved and bridled scarf joint in arcade plate and principal rafter above. Many joints have wrought iron ties.



Photo 52. Typical crown strut to collar detail. The use of the crown strut suggests a transitional roof between the earlier crown post and the later side purlin roofs. The final change in Essex appears to come at about 1580.



Photo 49. Typical detail of the collar with bare faced dovetail clasp the purlin to the principal rafter which reduces section through the joint.



Photo 56. Arcade post bracing to plate & tiebeam.



Photo 50. Wind braces in roof where they survive.



Photo 65. Apotropaic circle just visible on principal rafter facing to main doors in midstrete. Has partially completed radii to form the daisy pattern. Protection symbols are common in barns.