



Photo 215. View up to north east corner of truss 2, line C with mortise and lap for dragon tie across corner of building. This is the hip truss of the original construction.



Photo 213. Collar of hip truss with housing above for gablet collar. Frame weathered above this point.



Photo 211. Internal granary built into aisle in nineteenth century.