



Photo 145. Long view inside stables to north west. Note shadow of feed rack.



Photo 164. Typical purlin scarf joint.



Photo 166. Detail of truss structure.



Photo 203. Typical view inside an original opening.



Photo 25. Return wall of stable showing ends of feed rack and shadow shape.