

Building B. Main eighteenth century block from the north. Originally a window behind creeper.





Building B. View on east wall. shows two parallel breaks for original wide carriage entrance. Infilled vents either side.

Building B. North wall showing diamond set Tack Room stack and iron tie through building.



Building B. Detail showing one of infilled brick vents in east wall.



Detail of topplate bridled scarf visible in north wall near stack. Carpenters chiselled marks III.