


Building B. Hay Loft with view to west and access to gallery above Carthorse stable. Framed side purlin in area where stack goes through roof.



Gabled roofed timber framed dormered loading door to the farmyard. Good wide boarded unbraced door suggests eighteenth century as do the long fine hinges.



Cover to hay drop hatch (1 of 3) to hay racks below.



View towards carriage shed vertical ladder access with framed boarded infill and plaster above collars.