

Parsonage Farm, Parsonage Green, School Lane, Broomfield, Essex.



Building B. End wall of Carthorse stable, shows brick gable of adjoining build & a mixed infill around it.



View to rear, north, roof shows reused timber & poor structural features.



End wall with similar brickwork to main walls. Remains of vertical boarding survive with lacing pieces in wall.



Rear wall, north, with feed trough and rings for five horses. Shadows show where hay rack was fitted.



Upper level of east wall showing gallery to hay loft.



Lower section of east wall showing timber structure.



Plastered niche in front wall.



Tying rings on section of feed trough.



Harness hooks on east wall.