

Parsonage Farm, Parsonage Green, School Lane, Broomfield, Essex.



Building B, Granary. Detail of side purlin roof with collars to principle trusses and consistent size rafters. The raised ridge board was for a lead formed ridge.



View to front wall showing plastered finish most likely boarded below lacing pieces.



View to north west corner showing plastered walls and infilled eaves against rodent entry. Vertical timbers to walls with fillets for division boards.



Quantity slips pinned to beam showing last materials stored.



View to front south east corner showing broken brick joint suggesting Carthorse stable was originally longer. The large detail shows the same area on the outside with broken brick forming the end of the stable wall.



Granary wall

Stable wall