

**Parsonage Farm, Parsonage Green, School Lane, Broomfield, Essex.**



Building B west. Central Loose Box - to south/east.



Good roof, simple trusses, slate covered.



Brick floor at removed division wall.



Feed trough & marks for hay rack on wall.



Timber and boarded infill above removed division wall.



Goose yard beyond division with west door.



Western hipped end of building with door to Goose Yard.



View of area outside Goose yard door suggesting that the area was originally brick paved.