

Whitley House, Four Ash Hill, Baythorne End, Birdbrook. Essex.



Front south easterly view of the coach house. Note scar from C19 shelter shed roof and lowered main doorway.



Dog tooth detail under eaves. Flemish bond brick below.



Circular window to upper floor from rubbed bricks.



Diocletian window with rubbed brick arch, alternate bricks scored for lime putty joint.



Whitley House, Four Ash Hill, Baythorne End, Birdbrook. Essex.



Detail at main opening with rubbed semi-elliptical arched head flanked by pilasters with string course above surmounted by pedimented head detail in rubbed and moulded brick.



Detail of base of arched head.



Detail of top to pilaster.



South west elevation of building with high loading door and nineteenth century lean-to addition on the rear.



North east elevation from moated area. Infilled doorway at lower left hand side. Brick wall to lean-to most likely part of garden wall. Wall to left is nineteenth century rear wall of shelter sheds now removed.