

Appendix 1 Plates



Plate.1 General view of development area looking south-east.



Plate.2 General view of development area looking south-west.



Plate.3 Shot showing depth of deposit (113) cut by services [112] above and remnants of toilet wall footings.



Plate.4 Large brick manhole [125] sealed by made ground (113).



Plate.5 Depth of made ground (113) at western end of site below degraded tarmac (126), levelling (106), (124) and tarmac (108).



Plate.6 Shot showing depth of toilet wall footings and services in south-east corner of site.



Plate.7 shot showing depth of made ground (113) and levelling deposits after removal of Victorian wall footings (114) at base of trench at southern end of site.



Plate.8 Depth of made ground (113) sealed by (106), (124), (123) and tarmac (108) at northern end of site.