



Pl. 1 Position of the monitored pipe duct (looking south towards the porch, with the east wall of the tower in the foreground, right. Scales 2m and 0.25m).



Pl. 2 South face of the re-excavated duct, with the low walls of the concrete lined duct visible at the base of the excavation. The 19th century floor tiles have been laid above a layer of demolition material (101), which may extend behind the duct. (Looking south, scales 2m and 0.25m).



Pl. 3 The pipe duct extended to the west wall of the nave. To the north (right), the abrupt change in the stonework is at the south-east corner of the earlier east wall of the tower (looking west, scale 2m).