



Pl. 1 Location of the new development at The William Harrison School (looking south past the new site access towards the existing school buildings, with Middlefield Lane beyond the hedge to the left).



Pl. 2 The existing sports field and playing field area, with tape marking the site of the new school building (looking west from the Middlefield Lane entrance).





Pl. 3 Much of the development area was stripped of topsoil with a bulldozer (looking south-west).



Pl. 4 The stripped surface was trampled and disturbed by the machine tracks and was not in suitable condition for the identification of archaeological features (looking west).





Pl. 5 The stripped area (looking north).



Pl. 6 Detail of the surface left after topsoil removal (looking south towards the existing school buildings).





Pl. 7 A terram membrane was laid over the stripped area, and this was covered with crushed hardcore. The foundation trenches for the new school buildings were excavated from this level, only revealing undisturbed natural clay (looking north, scale 1m).



Pl. 8 Excavation of the sewer trench alongside the Middlefield Lane boundary (looking south).





Pl. 9 Topsoil and natural clay deposits visible in the sewer trench face (scale 1m).



Pl. 10 The contractors' site compound was stripped with an untoothed bucket, but even in these conditions no archaeological features were identified (looking south; the pipe trench beside the eastern boundary can be seen).