



Pl. 1 View of the development site, with the new foundation trench positions marked in white. (Looking north-west from the Main Street site entrance).




Pl. 2 North face of the contractors' Test Pit 2, showing soil with rubble overlying buried topsoil with naturally deposited sandy gravel and clay deposits below. (Looking north, scale 1m).



Pl. 3 Deposits visible in the western face of Trench 1 (the western foundation trench), towards the southern end of the site. Darker deposits survived to a greater depth at the northern end where the ground was higher. (Looking west, scale 1m).



Pl. 4 Deposits visible in the southern face of Trench 2 (the southern foundation trench). (Looking south, scale 1m).



Pl. 5 Deposits visible in the western face of Trench 3 (the south-eastern foundation trench). (Looking west, scale 1m).



Pl. 6 Deposits visible in the eastern face of Trench 5 (the eastern foundation trench). (Looking east, scale 1m).



Pl. 7 Deposits visible in the eastern face of Trench 6. (Looking east, scale 1m).

