



Amendments		
Issue No.	Date	Description
-	-	-
-	-	-

KEY

Areas of higher resistance anomalies within band of generally high resistance - may relate to structural remains or dumped building material

Band of high resistance - may relate to structural remains or dumped building material

Moderate resistance area anomaly - possible compacted ground

Moderate resistance area anomaly - possibly caused by changes in soil moisture content associated with service trench

Low resistance anomaly - possibly associated with service found in magnetometry survey

Very low resistance areas - possible geological/pedilological origin

Client

GIFFORD AND PARTNERS

Project Title

Job No.

2025

GEOPHYSICAL SURVEY

BUCKLEY'S FIELD, MIDDLEWICH

Subject

ABSTRACTION AND INTERPRETATION OF RESISTANCE ANOMALIES

STRATASCAN™

GEOPHYSICS FOR ARCHAEOLOGY AND ENGINEERING

VINEYARD HOUSE

UPPER HOOK ROAD

UPTON UPON SEVERN

UK

WR8 0SA

T: +44 (0)1684 592266

F: +44 (0)1684 594142

E: info@stratascan.co.uk

www.stratascan.co.uk

REGISTERED ORGANISATION IFA

Scale

1:500

0m 5 10 15 20 25m

Plot

A3

Checked by

SAS

Issue No.

01

Survey date

JULY 05

Drawn by

ELC

Figure No.

11