



328800



**Amendments**

Issue No.	Date	Description
-	-	-

**KEY**

- Linear anomalies - possible services or structural supports
- Strong complex and discrete responses - possible structural remains or debris
- Weak complex and discrete responses - possible structural debris and areas of ground disturbance
- Discrete and complex responses - possible evidence of fragmented structural remains
- Broad crested anomalies - possible structural remains
- Strong planar and complex anomalies - may relate to a buried surface with interspersed structural remains
- Weak planar and complex anomalies - may relate to a buried surface with interspersed structural remains
- Weak discrete anomalies - possibly relating to structural remains
- Conductive surfaces caused by inspection cover and gullies
- Area of reinforced concrete

0,25 Approximate depth to top of anomaly

Job No. **2076** Survey Date **OCT 05**

Client  
**BIRMINGHAM ARCHAEOLOGY**

Project Title  
**TUTBURY GLASSWORKS,  
STAFFORDSHIRE**

Subject  
**INTERPRETATION OF GPR  
ANOMALIES**

**STRATASCAN™**  
GEOPHYSICS FOR ARCHAEOLOGY  
AND ENGINEERING  
VINEYARD HOUSE  
UPPER HOOK ROAD  
UPTON UPON SEVERN  
UK  
WR8 0SA  
T: +44 (0)1684 592266  
F: +44 (0)1684 594142  
E: info@stratascan.co.uk  
www.stratascan.co.uk

Scale  
**1:200**

Plot <b>A1</b>	Checked by <b>PPB</b>	Issue No. <b>01</b>
Date <b>OCT 05</b>	Drawn by <b>HH</b>	Figure No. <b>12</b>