










Amendments		
Issue No.	Date	Description



ADDITIONAL AREAS
TO BE SURVEYED
BY GEOPHYSICAL
TECHNIQUES.

KEY	
	Discrete positive anomaly - possible pit
	Positive anomaly with associated negative response - ferrous object
	Magnetic disturbance - associated with pipe/cable
	Positive linear anomaly - possibly relating to agricultural activity
	Positive linear anomaly - cut feature of possible archaeological origin
	Negative linear anomaly - possibly indicating a bank or previous earthwork
	Area of magnetic debris - evidence of ground disturbance
	Area of magnetic disturbance - associated with nearby field boundaries, roads or services

Client

EXETER ARCHAEOLOGY

Project Title	Job No.	2155
GEOPHYSICAL SURVEY - WATER SEWAGE TREATMENT NEAR EXETER AIRPORT		
Subject	ABSTRACTION AND INTERPRETATION OF GRADIOMETER ANOMALIES AREA 2	

STRATASCAN™
GEOPHYSICS FOR ARCHAEOLOGY
AND ENGINEERING
VINEYARD HOUSE
UPPER HOOK ROAD
UPTON UPON SEVERN
UK
WR8 0SA
T: +44 (0)1684 592266
F: +44 (0)1684 594142
E: info@stratascan.co.uk
www.stratascan.co.uk

Scale 1:1250

Plot	Checked by	Issue No.
A3	SAS	01
Survey date	Drawn by	Figure No.
JUNE 06	NG/HH	12