

Road Maintenance Works at Walton Street, Oxford Archaeological Watching Brief Report

October 2019

Client: Skanska Oxford on behalf of Oxfordshire County Council

Issue No: 1

OA Reference No: OXWASEWB

NGR: SP 50956 06528





Client Name: Skanska Oxford/ Oxfordshire County Council

Client Ref No:. 9004068945 COPY

Document Title: Road Maintenance Works at Walton Street, Oxford

Document Type: Watching Brief Report

Grid Reference: SP 50956 06528

Planning Reference: Permitted Development

Site Code: OXWASE19 Invoice Code: **OXWASEWB**

Receiving Body: Oxfordshire County Museum Services

Accession No.: **OXCMS: 110**

OA Document File Location: X:\o\Oxford_Walton-Street_Sinkholes_WB

X:\o\Oxford_Walton-Street_Sinkholes_WB\010Geomatics OA Graphics File Location:

Issue No: 1

2019-10-23 Date:

Prepared by: Elizabeth Kennard (Assistant Supervisor) & Joakim Thomasson (Senior

Project Manager)

Gerry Thacker (Senior Project Manager) Checked by:

Edited by: Joakim Thomasson (Senior Project Manager)

Approved for Issue by: David Score (Head of Fieldwork)

Signature:

DavidScore

This document has been prepared for the titled project or named part thereof and should not be relied upon or used for any other project without an independent check being carried out as to its suitability and prior written authority of Oxford Archaeology being obtained. Oxford Archaeology accepts no responsibility or liability for the consequences of this document being used for a purpose other than the purposes for which it was commissioned. Any person/party using or relying on the document for such other purposes agrees and will by such use or reliance $be \ taken \ to \ confirm \ their \ agreement \ to \ indemnify \ Oxford \ Archaeology \ for \ all \ loss \ or \ damage \ resulting \ therefrom. \ Oxford \ Archaeology \ accepts$ no responsibility or liability for this document to any party other than the person/party by whom it was commissioned.

OA South OA East Janus House 15 Trafalgar Way Osney Mead Bar Hill Oxford Cambridge OX2 OES CB23 8SQ

t. +44 (0)1865 263 800 t. +44 (0)1223 850 500

> e. info@oxfordarch.co.uk w. oxfordarchaeology.com Oxford Archaeology is a registered Charity: No. 285627











OA North

Moor Lane

Lancaster LA1 1QD

Moor Lane Mills

t. +44 (0)1524 880 250

Mill 3

©Oxford Archaeology Ltd 23 October 2019



Road Maintenance Works at Walton Street, Oxford

Archaeological Watching Brief Report

Written by Elizabeth Kennard and Joakim Thomasson

With contributions from Robert McIntosh and illustrations by Matt Bradley and Magdalena Wachnik

Contents

Summ	ary		vii
Ackno	wledgements	3	viii
1	INTRO	DUCTION	1
1.1	Scope of wo	rk	1
1.2	Location, top	pography and geology	1
1.3	Archaeologic	cal and historical background	1
2	WATCH	ING BRIEF AIMS AND METHODOLOGY	2
2.1	Aims		2
2.2	Methodolog	y	2
3	RESULT	¯s	3
3.1	Introduction	and presentation of results	3
APPE	NDIX A	BIBLIOGRAPHY	4
APPE	NDIX B	SITE SUMMARY DETAILS	5



List of Figures

Figure 1 Site location map

Figure 2 Location of surveyed trenches (voids)

List of Plates

Plate 1 Identifying void 1
Plate 2 Backfilling void 1
Plate 3 Identifying void 2
Plate 4 Backfilling void 2



Summary

In August 2019, Oxford Archaeology was commissioned by Skanska on behalf of Oxford City Council to carry out a watching brief during road repair works following the appearance of underground cavities in Walton Street, Oxford. The site is located in the vicinity of the medieval settlement of Walton and Worcester College.

The machine excavations to locate and backfill the cavities were monitored. The works encountered modern backfill of service trenches underneath the existing hard standing. No archaeological deposits were observed or finds recovered.



Acknowledgements

Oxford Archaeology would like to thank Paul Roworth of Skanska Oxford for commissioning this project. Thanks are also extended to David Radford who monitored the work on behalf of Oxford City Council.

The project was managed for Oxford Archaeology by Joakim Thomasson and Carl Champness. The fieldwork was directed by Liz Kennard and Robert McIntosh. Survey and digitizing were carried out by Matt Bradley, plates and report was compiled by Magdalena Wachnik. Thanks is also extended to the OA staff that prepared the archive under the management of Nicola Scott.



1 INTRODUCTION

1.1 Scope of work

- 1.1.1 Oxford Archaeology (OA) was commissioned by Skanska Oxford on behalf of Oxford County Council to undertake an archaeological watching brief during road maintenance works in Walton Street, Oxford.
- 1.1.2 A number of underground cavities were detected during road repairs at Walton Street by Worcester College. The contractor Skanska contacted David Radford, the Oxford City Archaeologist, who recommended that the repair works should be monitored by an archaeologist. A specification for the archaeological watching brief was agreed with David Radford, the Oxford City Archaeologist (OA 2019); this document outlines how OA implemented those requirements.
- 1.1.3 All work was undertaken in accordance with local and national planning policies and Chartered Institute for Archaeologists Guidance (CIfA 2014).

1.2 Location, topography and geology

- 1.2.1 Walton Street runs from the district Jericho in the north (previously the medieval settlement of Walton) to Beaumont Street in the south. The site is located in the southern part of Walton Road, near Worcester College, north-west of Oxford historic core.
- 1.2.2 The geology of the area is mapped as the Oxford Clay Formation and West Walton Formation, mudstones of the Jurassic era, overlain by Summertown-Radley sand and gravel deposits in the north-eastern part of the site and Northmoor sand and gravel deposits in the remainder (BGS 2019).

1.3 Archaeological and historical background

1.3.1 The archaeological and historical background of the Oxford area has been described in the Written Scheme of Investigation (WSI) for the undertaken archaeological watching brief (OA 2019), and will not be referred here.

©Oxford Archaeology Ltd 1 23 October 2019



2 WATCHING BRIEF AIMS AND METHODOLOGY

2.1 Aims

- 2.1.1 The project aims were to monitor excavations in order to obtain information about the nature and depths of any below ground archaeological deposits that may survive within the site.
- 2.1.2 The specific aims and objectives of the watching brief were to determine or confirm the general nature of any remains present, to determine or confirm the approximate date or date range of any remains, by means of artefactual or other evidence, and to make available the results of the investigation.
- 2.1.3 Any remains of significance within Oxford are related to the Oxford City Archaeological research agendas (2011) for the relevant periods, and Solent-Thames Research Framework for the Historic Environment (Hey & Hind 2014).

2.2 Methodology

2.2.1 A mechanical excavator was used to locate the extent of the cavities, which were found to be caused by leaking water services. The works were carried out as an emergency measure to stabilise the street. The hardstanding was removed, and the exposed cavities were immediately filled with gravel. Due to the sometime limited size of the voids, as well as the instability of the trench sides, it was not safe to enter the trenches. Monitoring was therefore undertaken from stable ground adjacent to the trenches.

©Oxford Archaeology Ltd 2 23 October 2019



3 RESULTS

3.1 Introduction and presentation of results

- 3.1.1 Altogether twelve voids were discovered in Walton Street between Walton Crescent in the north and Beaumont Street in the south, labelled as trench 1-12 on Figure 2.
- 3.1.2 The cavities were between 15.5m and 2m in length, 2m and 1m in width and 2.2m and 0.8m in depth. All the voids were located in backfill of existing underground services.
- 3.1.3 Cavities 1 and 2 (Fig. 2, Plate 1-4) had the potential to reveal archaeological deposits, and were monitored by an archaeologist. Once it was understood that all voids where within the backfill of existing services, the watching brief was discontinued.
- 3.1.4 Although deeper features such as pits and wells would have survived modern truncation, no observations of preserved archaeological deposits or finds material were made during the watching brief.



APPENDIX A BIBLIOGRAPHY

BGS, 2019. British Geological Survey Viewer. Available at: http://mapapps.bgs.ac.uk/geologyofbritain/home.html [accessed July 2019].

CIFA 2014. Standard and Guidance for an Archaeological Watching Brief. Chartered Institute for Archaeologists, Reading.

Oxford Archaeology 2019. Road Maintenance Works at Walton Street, Oxford. Written Scheme of Investigation Archaeological Watching Brief. OA Reference No: 23850.



APPENDIX B SITE SUMMARY DETAILS

Site name: Road Maintenance Works at Walton Street, Oxford

Site code: OXWASE19
Grid Reference SP 50956 06528
Type: Watching Brief

Date and duration: August 2019 (2 days attendance)

Area of Site -

Location of archive: The archive is currently held at OA, Janus House, Osney Mead,

Oxford and will be deposited with an appropriate repository in

due course.

Summary of Results: In August 2019, Oxford Archaeology was commissioned by

Skanska on behalf of Oxford City Council to carry out a watching brief during road repair works following the appearance of underground cavities in Walton Street, Oxford. The site is located in the vicinity of the medieval settlement of Walton and

Worcester College.

The machine excavations to locate and backfill the cavities were monitored. The works encountered modern backfill of service trenches underneath the existing hard standing. No archaeological deposits were observed or finds recovered.




Figure 1: Site location






Plate 1: Identifying void 1



Plate 2: Backfilling void 1



Plate 3: Identifying void 2



Plate 4: Backfilling void 2





Head Office/Registered Office/ OA South

Janus House Osney Mead Oxford OX20ES

t:+44(0)1865 263 800 f:+44 (0)1865 793 496 e:info@oxfordarchaeology.com w:http://oxfordarchaeology.com

OA North

Mill3 MoorLane LancasterLA11QD

t:+44(0)1524 541000 f:+44(0)1524 848606 e:oanorth@oxfordarchaeology.com w:http://oxfordarchaeology.com

OAEast

15 Trafalgar Way Bar Hill Cambridgeshire CB238SQ

t:+44(0)1223 850500 e:oaeast@oxfordarchaeology.com w:http://oxfordarchaeology.com



Director: Gill Hey, BA PhD FSA MClfA Oxford Archaeology Ltd is a Private Limited Company, N°: 1618597 and a Registered Charity, N°: 285627