

Photo 1: View of Old Gate from the old bridge; no.19 is the lower building (film 2, film 6)



Photo 2: View of the site from the south-east, across the Hebden Water (film 2, film 4)



Photo 3: The group of former cottages, from the south-east across the Hebden Water (film 2, film 5)




Photo 4: Old Gate from West End Bridge, looking north-east, with the site largely hidden by adjacent buildings (film 2, film 7)



Photo 5: Cottages 1 and 2 during demolition (film 5, film 1)



Photo 6: The remaining ventilator of 1938 (film 2, film 9)



Photo 7: The former cottages, from the south (film 1, film 16)



Photo 8: Cottage 1: ground floor openings in front elevation (film 1, film 17)



Photo 9: Cottage 4: ground floor openings in front elevation (film 2, film 1)



Photo 10: Cottage 2: interior of front ground floor window and former doorway (at left) (film 1, film 1)



Photo 11: Cottage 2: hinge pintle of former front doorway (film 4, film 6)



Photo 12: Cottage 2: interior of front ground floor window (film 1, film 3)



Photo 13: Cottage 3: interior of front ground floor window (film 1, film 5)





Photo 14: Cottage 4: interior of front ground floor window and former doorway (at left) (film 1, film 9)



Photo 15: Cottage 4: interior of front first floor window (film 1, film 13)



Photo 16: The former cottages, from the north-east (film 1, film 18)



Photo 11: Cottage 2: hinge pintle of former front doorway (film 4, film 6)



Photo 18: Cottage 2: rear, first floor window (film 3, film 10)



Photo 19: The narrow rear yard behind cottage 2, from the north-east (film 3, film 7)



Photo 21: Cottage 4: rear first floor window (film 3, film 4)



Photo 20: Cottage 3: rear first floor window, altered to doorway (film 3, film 6)



Photo 22: Cottage 3: rear first floor window, inserted 1938 (film 3, film 9)



Photo 23: Cottage 1: south-west gable interior, during demolition (film 6, film 1)



Photo 24: Cottage 1: south-west gable interior, during demolition  
(film 5, film 4)



Photo 25: Cottage 1: interior, during demolition (film 5, film 5)



Photo 26: Cottage 1: ground floor fireplace, in south-west gable (film 6, film 2)



Photo 27: Cottage 1: detail of mantelshelf to ground floor fireplace (film 6, film 7)



Photo 28: Cottage 1: detail of mantelshelf to ground floor fireplace (film 6, film 8)





Photo 30: Cottage 1: south-west gable on ground floor, showing remains of oak timber, cut by modern doorway (film 6, film 4)



Photo 29: Cottage 1: ground floor fireplace, in south-west gable (film 5, film 15)