

Photo 1: Building 1: external view of phase 1 wall in west side (film 5, frame 5)




Photo 2: Building 1: internal view of phase 1 wall in west side (film 4, frame 9)



Photo 3: Doorway with basket arch in phase 1 wall, external view (film 5, frame 4)




Photo 4: Doorway with basket arch in phase 1 wall, internal view (film 5, frame 2)




Photo 5: Building 1: external view of phase 1 wall in west side (film 5, frame 6)




Photo 6: Building 1: internal view of phase 1 wall in west side (film 5, frame 1)



Photo 7: Building 1: external view of arched doorway in phase 1 wall in west side, with later phase to left (film 1, frame 12)



Photo 8: Building 1: internal view of phase 1 wall in west side, with former position of blast furnaces to left (film 4, frame 8)



Photo 9: Building 1: internal view of west side, showing former position of blast furnaces (steel stanchions) and columns (film 3, frame 8)




Photo 10: Building 1: internal view of large colonnade, west side (film 3, frame 6)







Photo 12: Building 1/3: detail of bracket for roof truss over Building 3 (film 5, frame 14)




Photo 13: Building 1: external view of west wall with tops of furnace openings at ground level (film 1, frame 13)



Photo 14: Building 1: internal view of west wall, with former openings to furnaces (film 4, frame 11)



Photo 15: Building 1: external view of west wall, north end, with straight joint and inserted colonnade (film 1, frame 11)




Photo 16: Building 1: external view of west wall, showing inserted colonnade (film 1, frame 14)




Photo 17: Building 1: external view of west wall, showing inserted colonnade (film 1, frame 15)



Photo 18: Building 1: internal view of west wall, showing inserted colonnade (film 4, frame 12)




Photo 19: Building 1: internal view of west wall, showing inserted colonnade (film 4, frame 18)



Photo 20: Building 1: external view of west wall, north end, showing arch slighted by inserted colonnade (film 1, frame 17)




Photo 21: Building 1: internal view of west wall, north end, showing arch slighted by inserted colonnade (film 4, frame 13)



Photo 22: Building 1: external view of south wall, showing arched former window and floor of modern building above (film 3, frame 17)



Photo 23: Buildings 1 and 3, from the south-west, with modern annex at right (film 1, frame 5)




Photo 24: Building 1: enclosed area at ground floor, by south wall, from the west (film 3, frame 14)




Photo 25: Building 1: enclosed area at ground floor, by south wall, from the east (former coke ovens to left?) (film 3, frame 16)



Photo 26: Building 1: interior view of south wall (film 3, frame 2)




Photo 27: Building 1: interior view of south-west corner (film 3, frame 7)



Photo 28: Building 1: interior view of south-east corner, with blocked window and corner flue (film 3, frame 4)




Photo 29: Building 1: interior view of south wall, showing inserted opening with column (film 3, frame 5)



Photo 30: Building 1 (left) and Building 2 (right), from the south-east (film 1, frame 1)



Photo 31: Building 1: external view of east wall, south end (film 1, frame 2)



Photo 32: Building 1: external view of east wall, south end (film 1, frame 3)




Photo 33: Building 1: internal view of east wall, south end (film 3, frame 11)




Photo 34: Building 1: interior view of one of two arched former openings in east wall, south end (film 3, frame 12)




Photo 35: Building 1: detail of iron "socket" in east wall, next to straight joint (film 3, frame 13)



Photo 36: Building 1: external view of east wall, now within Building 2 (film 2, frame 1)




Photo 37: Building 1: external view of east wall, now within Building 2 (film 2, frame 12)



Photo 38: Building 1: external view of east wall, now within Building 2, with mid-height arched windows (film 1, frame 18)



Photo 39: Building 1: external view of east wall, now within Building 2, with blocked, tall arched doorway (film 2, frame 9)




Photo 40: Building 1: external view of east wall, now within Building 2 (film 2, frame 2)



Photo 41: Building 1: external view of east wall, now within Building 2 (film 2, frame 4)




Photo 42: Building 1: external view of east wall, north end, now within Building 2 (film 2, frame 10)



Photo 43: Building 1: internal view of east wall, from the south-west (film 3, frame 10)



Photo 44: Building 1: internal view of east wall (film 4, frame 6)



Photo 45: Building 1: internal view of east wall (film 4, frame 5)




Photo 46: Building 1: internal view of east wall (film 4, frame 2)




Photo 47: Building 1: external view of doorway at north end of east wall (film 2, frame 11)




Photo 48: Building 1: detail of external jamb of doorway at north end of east wall (film 2, frame 16)




Photo 49: Building 1: internal view of doorway at north end of east wall (film 4, frame 1)




Photo 50: Building 1: external detail of refractory jamb to blocked opening to former furnace, east wall (film 2, frame 5)




Photo 51: Building 1: internal view of blocked opening to former furnace, east wall (film 4, frame 3)



Photo 52: Building 1: internal view of north end (film 4, frame 14)



Photo 53: Building 1: internal view of east wall, from the north-west (film 4, frame 15)



Photo 54: Building 1: internal view of east wall, from the south-west (film 4, frame 7)



Photo 55: Building 1: internal view of west wall, from the north-east (film 4, frame 17)



Photo 56: Building 2: interior, from the south-west (film 2, frame 17)



Photo 57: Building 2: view up towards roof, from the south (film 3, frame 1)



Photo 58: Building 2: internal view of east wall, from the south-west (film 2, frame 18)





Photo 59: Building 2: wall bearing box in west wall (film 2, frame 14)



Photo 60: Building 3: internal view of south end (film 5, frame 12)






Photo 62: Building 3: external view of west wall, south end (film 1, frame 6)




Photo 63: Building 3: internal view of west wall, south end (film 5, frame 11)



Photo 64: Building 3: interior at south end (film 5, frame 10)




Photo 65: Building 3: interior, from the south-east (film 5, frame 16)



Photo 66: Building 3: external view of west wall, north end (film 1, frame 8)




Photo 67: Building 3: external view of west wall, north end (film 1, frame 7)



Photo 68: Building 3: external view of north wall (film 1, frame 10)



Photo 69: Building 3: internal view of west wall, north end (film 5, frame 8)



Photo 70: Building 3: interior at north end (film 5, frame 7)