



Photo 1: The barn and shippon from the west



Photo 2: North-west elevation of barn



Photo 3: Detail of blocked doorway to former shippon, in north-west elevation of barn




Photo 4: South-west gable of the barn



Photo 5: Detail of kneeler at south-west corner of barn




Photo 6: The barn and shippon from the south-west



Photo 7: South-east elevation of barn and shippon, from the south



Photo 8: South-east elevation of barn




Photo 9: Detail of main barn entrance in south-east elevation




Photo 10: Interior of barn: north-west doorway



Photo 11: Interior of barn: view towards north-west doorway from the east



Photo 12: Interior of barn: view towards south-east porch and entrance



Photo 13: Interior of barn: view towards south-west corner (former shippon area); modern timbers are to keep hay dry



Photo 14: Interior of barn: north-west corner, with blocked doorway.



Photo 15: Interior of barn: view towards west end



Photo 16: Interior of barn: view towards south-east corner



Photo 17: Interior of barn: roof trusses, from the east



Photo 18: Interior of barn: east roof truss, from the west



Photo 19: North-west elevation of 1926 shippon, from the west



Photo 20: Detail of south-east elevation of 1926 shippon



Photo 21: Added shippon, from the north-east




Photo 22: Added shippon, from the north



Photo 23: Barn and added shippon, from the east



Photo 24: South-east elevation of 1926 shippon



Photo 25: Interior of shippon: view down feeding passage, from the east



Photo 26: Interior of shippon: view of stalls in south-east side, from the east



Photo 27: Interior of shippon: view of stalls in north-west side, and former stable, from the east



Photo 28: Interior of shippon: view of stalls in south-east side, from the west



Photo 29: Interior of shippon: former stable, from the north.
Modern stalls for cows but original timber partition above trough



Photo 30: Interior of shippon: detail of date and initials in floor: "J W 1926" (J Whitworth)



Photo 31: Interior of shippon: west roof truss and former stable, from the east



Photo 32: Interior of shippon: east roof truss, from the south-west



Photo 33: General view of the site, from the east



Photo 34: Stone-built shed to east of shippon, from the north-west




Photo 35: North-east end of 1926 shippon, and outbuildings to east



Photo 36: View of barn and shippon, from the south-east